F281-629	(Rev. 5/92)	15-5078					•
PROPOSAI	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	is, LLC ara Ave., Ste. #208 IV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
FOR: TIME & DATE:	and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan Underwater LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 754	Texas Tank S 103 Stacy Dr. Whitehouse, T	Chris Con 59 Stone Antonio,
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		Marc LLLC P.O. Conc	H2(903 Las	Tay 115 Fari	Tex 103 Wh	EJ (2006
-	2015 TANK INSPECTION & CLEANING PRICING LIST				-	-	
	ASR Clearwell No. 1 Potable Water Tank						
	3.0 MG; 179 feet diam.; 16.7 feet overall height						
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning Cost		500.00	1,000.00	7,500.00	7,299.00	
	Drained Cleaning cost per additional 1" of sedimentation		400.00	100.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	2,000.00	315.00	499.00	
	Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		2,000.00 200.00	2,500.00 500.00	1,400.00 115.00	4,599.00 450.00	
1	TOTAL		3,460.00	6,600.00	9,590.00	13,796.00	
•	Austin Potable Water Elevated Storage Tank		3,400.00	0,000.00	2,520.00	13,770.00	
	1.5 MG; 88 feet diam.; 138 feet overall height						
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning Cost		500.00	1,000.00	9,630.00	4,899.00	
	Drained Cleaning cost per additional 1" of sedimentation			50.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	2,000.00	315.00	499.00	
	Cleaning Cost In-service (not drained)		2,000.00	2,500.00	1,300.00	2,499.00	8
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	115.00	450.00	$\frac{N}{N}$
2	TOTAL		3,460.00	6,300.00	11,620.00	9,296.00	9 5
	Bitters Potable Water Ground Storage Tank						BID NOT TABULATED NDUM NO. 2 NOT RETURNED
	5 MG; 165.0 feet diam.; 33.0 feet overall height Inspection Cost Drained		360.00	500.00	120.00	499.00	7.7.
	Drained Cleaning cost		500.00	1,000.00	11,910.00	8,599.00	BC NC
	Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation		300.00	100.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	2,000.00	315.00	499.00	T ON
	Cleaning Cost In-service (not-drained)		3,500.00	2,500.00	1,550.00	7,665.00	ΣΣ
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	500.00	190.00	450.00	9 9
3	TOTAL		4,960.00	6,600.00	14,225.00	18,162.00	m K
	Devine Reuse Water Elevated Storage Tank						BID NOT T ADDENDUM NO.
	1.2 MG; 84 feet diam.; 43 fee bowl height; 83 feet overall height						IV
	Inspection Cost Drained		360.00	500.00	120.00	575.00	
	Drained Cleaning cost		500.00	1,000.00	8,630.00	10,250.00	
	Drained Cleaning cost per additional 1" of sedimentation		400.00	50.00	140.00	450.00	
	Inspection Cost In-service (not drained) Cleaning Cost In-service (not-drained)		400.00 2,000.00	2,000.00 2,500.00	315.00 1,400.00	575.00 4,950.00	
	Underwater Cleaning cost per additional 1" of sedimentation		2,000.00	2,300.00	140.00	4,930.00	
4	TOTAL		3,460.00	6,300.00	10,745.00	17,250.00	
· ·	East Houston Reuse Water Ground Storage Tank		2,400.00	0,500.00	10,740.00	17,200.00	
	1.0 MG; 75 feet diam.; 32 feet overall height						
	Inspection Cost Drained		360.00	500.00	120.00	575.00	
	Drained Cleaning cost		500.00	1,000.00	4,787.00	8,199.00	
	Drained Cleaning cost per additional 1" of sedimentation			100.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	2,000.00	315.00	575.00	
	Cleaning Cost In-service (no drained)		2,000.00	2,500.00	1,400.00	5,250.00	
_	Underwater Cleaning cost per additional 1" of sedimentation		200.00	500.00	140.00	450.00	
5	TOTAL		3,460.00	6,600.00	6,902.00	15,499.00	

F281-629 (Rev. 5/92)	15-5078			ī		ı
SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	LLC Ave., Ste. #208 89117	, Inc. t Rd. K 75442	vices : 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
PROPOSAL Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection TIME & (March 1, 2015 through December 31, 2015 DATE: 3:00 p.m., February 25, 2015		Marcan Underw LLC P.O. Box 2591 Concroe, TX 77	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 754	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	hris Contra 9 Stone Oa Antonio, T
		Marc LLC P.O. Conc	120 030 'as'	ayl 152 arm	exa 03 : Vhit	2J C 065
Foster Potable Water Elevated Storage Tank 2.0 MG; 105 feet diam; 36 feet bowl height; 150+/- feet overall height Inspection Cost Drained		360.00	500.00	120.00	499.00	д (4 07
Drained Cleaning cost		500.00	1,000.00	9,063.00	5,299.00	
Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained)		400.00 2,000.00	50.00 2,000.00 2,500.00	140.00 315.00 1,400.00	450.00 499.00 2,699.00	
Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 3,460.00	250.00 6,300.00	140.00 11,178.00	450.00 9,896.00	
Grissom Potable Water Elevated Storage Tank 2.5 MG; 102 feet diam.; 49.6 feet bowl height; 185 feet overall height Inspection Cost Drained Drained Cleaning cost		360.00 500.00	500.00 1,000.00	120.00 10,630.00	499.00 5,899.00	
Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained)		400.00	50.00 2,000.00	140.00 315.00	450.00 499.00	
Cleaning Cost In-service (not drained)		2,100.00	2,500.00	1,400.00	2,999.00	Ω
Underwater Cleaning cost per additional 1" of sedimentation 7 TOTAL		200.00 3,560.00	250.00 6,300.00	140.00 12,745.00	450.00 10,796.00	%NE
Hildebrand Potable Water Elevated Storage Tank		3,300.00	0,500.00	12,743.00	10,770.00	E IOI
2 MG; 95.0 feet diam.; 45 feet bowl height; 119 feet overall height Inspection Cost Drained Drained Cleaning cost		360.00 500.00	500.00 1,000.00	120.00 10,630.00	499.00 5,299.00	BID NOT TABULATED NDUM NO. 2 NOT RETURNED
Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained)		400.00 2,000.00	50.00 2,000.00 2,500.00	140.00 315.00 1,400.00	450.00 499.00 2,699.00	BID NOT TA ADDENDUM NO. 2
Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	I OI
8 TOTAL Inwood Potable Water Ground Storage Tank		3,460.00	6,300.00	12,745.00	9,896.00	B DEN.
1.2 MG; 80 feet diam; 35 feet overall height Inspection Cost Drained Drained Cleaning cost		360.00 500.00	250.00 1,000.00	120.00 4,787.00	499.00 4,699.00	ADE
Drained Cleaning cost per additional 1" of sedimentation			50.00	140.00	450.00	
Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained)		400.00 2,100.00	1,000.00 2,000.00	315.00 1,300.00	499.00 2,450.00	
Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00 4,550.00	140.00 6,802.00	450.00 9,047.00	
9 TOTAL Pearsall Reuse Water Ground Storage Tank		3,560.00	4,330.00	0,002.00	9,047.00	
2.5 MG; 120 fee diam.; 33 feet overall height		240.00	500.00	120.00	555.00	
Inspection Cost Drained Drained Cleaning cost		360.00 500.00	500.00 1,000.00	120.00 7,500.00	575.00 10,950.00	
Drained Cleaning cost per additional 1" of sedimentation			100.00	165.00	450.00	
Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained)		400.00 2,500.00	2,000.00 2,500.00	315.00 1,500.00	575.00 6,499.00	
Underwater Cleaning cost per additional 1" of sedimentation		2,300.00	500.00	165.00	450.00	
10 TOTAL		3,960.00	6,600.00	9,765.00	19,499.00	

SAN ANTONIO WATER SYSTEM 20 20 20 20 20 20 20 2	F281-629	(Rev. 5/92)	15-5078					
Fins Rd. Reuse Water Ground Storage Tank 3 Mor. 9 Rect dism.; 80 Feet overall height 360.00 250.00 120.00 575.00 120.00 12	PROPOSAL	P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning		derwater Services, 591 X 77305	, Ste.	ving, Inc. But Rd. e, TX 75442	Services Dr. 5, TX 75791	ntracting, Inc. e Oak Pkwy #804 o, TX 78258
Fins Rd. Reuse Water Ground Storage Tank 3 Mor. 9 Rect dism.; 80 Feet overall height 360.00 250.00 120.00 575.00 120.00 12	TIME &	(March 1, 2015 through December 31, 2015		arcan Uno JC O. Box 25 oncroe, T	20 Solutic 330 W. Sa as Vegas,	ıylor'd Di 52 Lester ırmersvill	xas Tank 33 Stacy E hitehouse	Chris Co 1659 Ston In Antoni
3 MG; 84 feet diam; 80 feet overall height 360.00 250.00 120.00 575.00 Drained Cleaning cost per additional 1" of sedimentation 400.00 100.000 315.00 375.00 120.00 12.450.00 12.00 14.000 14.500.00 12.00 14.000 14.500.00 12.00 14.000 14.500.00 12.00 14.000 14.500.00 12.00 14.000 14.500.00 12.00 14.000	ПЕМ NO.		ı	ZUMO	L 90 H	T2 11 F2	₹ 2 ¥	S S E
Amhurst Potable Water Elevated Storage Tank 0.8 MG, 62 feet diam; 110 feet overall height; 10 feet overall height;	11	3 MG; 84 feet diam.; 80 feet overall height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		500.00 400.00 3,000.00 200.00	1,000.00 50.00 1,000.00 2,000.00 250.00	9,000.00 140.00 315.00 1,400.00 140.00	12,450.00 450.00 575.00 9,350.00 450.00	
0.8 MG, 62 feet diam; 110 feet overall height; 18pection Cost Drained Cleaning cost 360.00 500.00 120.00 4.99.00 120.00 4.99.00 120.00 4.99.00 120.00				4,460.00	4,550.00	11,115.00	23,850.00	
Underwater Cleaning cost per additional 1" of sedimentation 20,000 25,000 140,00 450,00 2,860,00 2,860,00 2,800,00		0.8 MG, 62 feet diam.; 110 feet overall height; Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained)		500.00 400.00	1,000.00 50.00 2,000.00	7,500.00 140.00 315.00	4,499.00 450.00 499.00	
TOTAL 2,860.00 6,300.00 9,515.00 8,596.00					-		· ·	0
Inspection Cost In-service (not drained)	12							Ē
Inspection Cost In-service (not drained)				,	- ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	.,	
Inspection Cost In-service (not drained)								ETA
Inspection Cost In-service (not drained)				360.00	150.00	120.00		LA]
Inspection Cost In-service (not drained)		· · · · · · · · · · · · · · · · · · ·		500.00			· ·	2 G
Echo Mountain Potable Water Elevated Storage Tank 2.5 MG, 105 feet diam.; 155 feet overall height 155 feet overall h				400.00				
Echo Mountain Potable Water Elevated Storage Tank 2.5 MG, 105 feet diam.; 155 feet overall height 155 feet overall h								NON
Echo Mountain Potable Water Elevated Storage Tank 2.5 MG, 105 feet diam.; 155 feet overall height 155 feet overall h					-			N M
Echo Mountain Potable Water Elevated Storage Tank 2.5 MG, 105 feet diam.; 155 feet overall height 155 feet overall h	13							81D
Inspection Cost Drained Cleaning cost 360.00 500.00 120.00 499.00 120.00 499.00 120.00		Echo Mountain Potable Water Elevated Storage Tank		·		·	·	
Inspection Cost Drained Cleaning cost 360.00 500.00 120.00 499.00 120.00 499.00 120.00		2.5 MG, 105 feet diam.; 155 feet overall height						IQ.
Drained Cleaning cost per additional 1" of sedimentation								4
Inspection Cost In-service (not drained)		e e e e e e e e e e e e e e e e e e e		500.00		,	· ·	
Cleaning Cost In-service (not drained) 2,100.00 2,500.00 1,400.00 2,999.00		* *		400.00				
Underwater Cleaning cost per additional 1" of sedimentation 200.00 250.00 140.00 450.00		1						
TOTAL 3,560.00 6,300.00 12,745.00 10,796.00								
0.5 MG, 55 feet diam.; 84.5 feet overall height 360.00 500.00 120.00 499.00 Inspection Cost Drained 500.00 1,000.00 8,000.00 4,299.00 Drained Cleaning cost per additional 1" of sedimentation 50.00 140.00 450.00 Inspection Cost In-service (not drained) 400.00 2,000.00 290.00 499.00 Cleaning Cost In-service (not drained) 1,500.00 2,500.00 1,300.00 2,199.00 Underwater Cleaning cost per additional 1" of sedimentation 200.00 250.00 140.00 450.00	14							
Drained Cleaning cost 500.00 1,000.00 8,000.00 4,299.00 Drained Cleaning cost per additional 1" of sedimentation 50.00 140.00 450.00 Inspection Cost In-service (not drained) 400.00 2,000.00 290.00 499.00 Cleaning Cost In-service (not drained) 1,500.00 2,500.00 1,300.00 2,199.00 Underwater Cleaning cost per additional 1" of sedimentation 200.00 250.00 140.00 450.00		8						
Drained Cleaning cost per additional 1" of sedimentation 50.00 140.00 450.00 18 pection Cost In-service (not drained) 400.00 2,000.00 290.00 499.00 1,500.00 2,500.00 1,300.00 2,199.00 1,000 2,199.00 1,000 2,199.00 1,000 2,199.00 1,000 1		1				120.00		
Inspection Cost In-service (not drained) 400.00 2,000.00 290.00 499.00 Cleaning Cost In-service (not drained) 1,500.00 2,500.00 1,300.00 2,199.00 Underwater Cleaning cost per additional 1" of sedimentation 200.00 250.00 140.00 450.00				500.00			· ·	
Cleaning Cost In-service (not drained) 1,500.00 2,500.00 1,300.00 2,199.00 Underwater Cleaning cost per additional 1" of sedimentation 200.00 250.00 140.00 450.00				400.00				
Underwater Cleaning cost per additional 1" of sedimentation 200.00 250.00 140.00 450.00					-			
				·				
	15	TOTAL		2,960.00	6,300.00	9,990.00	8,396.00	

F201-029	(Rev. 5/92)	15-5076	i	~ 1	ĺ	ĺ	ı
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Fexas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
PROPOSAL	Annual Contract for Potable and Reuse Water Storage Tank Cleaning		erw	ns, l ara IV	ing Bur T.	Ser TX	oa Oa T.
FOR:	and Inspection		Marcan Under LLC P.O. Box 2591 Concroe, TX 7	Sah Sah S, N	Div.	Texas Tank S 103 Stacy Dr. Whitehouse, ⁷	Con one nio,
TIME &	(March 1, 2015 through December 31, 2015		ox	olu N. 3 ega	d I	Tar acy nou	is C Stc
DATE:	3:00 p.m., February 25, 2015		C C B C D C D C C	0 S 30 V	rlor 52 I me	Texas Tank 103 Stacy D Whitehouse	Chr 559 1 Au
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		Marc LLLC P.O. Conc	H20 903 Las	Tay 115 Far	Tex 103 Wh	EJ (206
	New World Potable Water Elevated Storage Tank						- (1 - 2
	2.0 MG, 70 feet diam.; 164 feet overall height						
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	10,252.00	5,299.00	
	Drained Cleaning cost per additional 1" of sedimentation		300.00	50.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	2,000.00	315.00	499.00	
	Cleaning Cost In-service (not drained)		2,000.00	2,500.00	1,400.00	2,699.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
16	TOTAL		3,460.00	6,300.00	12,367.00	9,896.00	
	Sea World Potable Water Ground Storage Tank		2,100.00	0,200.00	12,007100	3,030.00	
	2 MG, 85 feet diam.; 50 feet overall height;						
	Inspection Cost Drained		360.00	250.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	8,192.00	4,999.00	
	Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation		300.00	50.00	140.00	4,999.00	
	Inspection Cost In-service (not drained)		400.00	1,000.00	315.00	499.00	
	*				1,300.00		
	Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		2,500.00 200.00	2,000.00 250.00	1,300.00	2,650.00 450.00	О
17	TOTAL		3,960.00	4,550.00	10,207.00	9,547.00	Ä
17	Texas Ranch Park Prestressed Concrete Potable Water Ground Storage Tank		3,200.00	4,330.00	10,207.00	9,347.00	2 X
	0						百日
	2.0 MG, 103 feet diam.; 32 feet overall height		260.00	500.00	120.00	400.00	AT R
	Inspection Cost Drained		360.00	500.00	120.00	499.00	15.0
	Draining Cleaning cost		500.00	1,000.00	8,192.00	4,999.00	AB N
	Drained Cleaning cost per additional 1" of sedimentation		400.00	100.00	140.00 315.00	450.00	0.0
	Inspection Cost In-service (not drained)		400.00	2,000.00		499.00	<u>5</u> Ž
	Cleaning Cost In-service (not drained)		2,500.00	2,500.00	1,400.00	2,650.00	ZZ
18	Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 3,960.00	500.00 6,600.00	140.00 10,307.00	450.00 9,547.00	BID NOT TABULATED NDUM NO. 2 NOT RETU
10			3,900.00	0,000.00	10,307.00	9,547.00	E
	Texas Ranch Park Welded Steel Potable Water Ground Storage Tank						BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
	0.25 MG, 54 feet diam.; 15 feet overall height		260.00	250.00	100.00	400.00	A
	Inspection Cost Drained		360.00	250.00	120.00	499.00	
	Draining Cleaning cost		500.00	1,000.00	3,719.00	3,499.00	
	Drained Cleaning cost per additional 1" of sedimentation		400.00	50.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	1,000.00	280.00	499.00	
	Cleaning Cost In-service (not drained)		1,100.00 200.00	2,000.00 250.00	1,000.00	1,899.00	
10	Underwater Cleaning cost per additional 1" of sedimentation				140.00	450.00	
19	TOTAL		2,560.00	4,550.00	5,399.00	7,296.00	
	West Avenue Potable Water Elevated Storage Tank						
	0.5 MG, 50 feet diam.; 145 feet overall height		250.00	500.00	100.00	100.00	
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	10,000.00	3,899.00	
	Drained Cleaning cost per additional 1" of sedimentation		100 5	100.00	140.00	450.00	
	Inspection Cost In-service (not drained)		400.00	2,000.00	315.00	499.00	
	Cleaning Cost In-service (not drained)		1,500.00	2,500.00	1,400.00	2,150.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	50.00	140.00	450.00	
20	TOTAL		2,960.00	6,150.00	12,115.00	7,947.00	

F281-629	(Rev. 5/92)	15-5078	,				
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015 DESCRIPTION AND APPROXIMATE QUANTITY		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
21	Minor Repair (Item F) Hourly Rate for 40 Hours		250.00 10,000.00	50.00 2,000.00	235.00 9,400.00	350.00 14,000.00	
22	Emergency Services (Item E) Mobilization 4 each Hourly Rate for 60 Hours TOTAL		250.00 15,000.00	250.00 1,000.00 50.00 3,000.00	500.00 2,000.00 150.00 9,000.00	1,150.00 4,600.00 450.00 27,000.00	
	TOTAL			4,000.00	11,000.00	31,600.00	NED
	TOTAL AMOUNT FOR YEAR 2015 (ITEMS 1-22) 2016 TANK INSPECTION & CLEANING PRICING LIST		95,000.00	122,800.00	224,557.00	282,004.00	ABULATED 2 NOT RETURNED
1	34th St. Potable Water Ground Storage Tank 5 MG, 164.5 Feet Diam.; 44.3 Feet Overal Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 6,000.00 200.00 7,460.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00 6,500.00	120.00 11,000.00 190.00 315.00 3,800.00 190.00 15,615.00	499.00 8,599.00 450.00 499.00 7,665.00 450.00 18,162.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETU
2	Anderson Potable Water Ground Storage Tank No. 1 7.5 MG, 165 Feet Diam.; 48 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 7,000.00 200.00 8,460.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00 6,600.00	120.00 14,972.00 190.00 315.00 3,700.00 190.00 19,487.00	499.00 13,950.00 450.00 499.00 11,950.00 450.00 27,798.00	

F281-629 (Rev. 5/92) 15-5078							
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	, LLC ra Ave., Ste. #208 7 89117	g, Inc. urt Rd. IX 75442	srvices X 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
PROPOSAL FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan Underwater LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy # San Antonio, TX 78258
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		M II M	7 HZ	Та 11 Fа	Te 10 W	EJ C 2065 San
3	ASR Clearwell No. 2 Potable Water Ground Storage Tank 7.5 MG, 227 Feet Diam.; 47.5 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 7,000.00 200.00 8,460.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00 6,600.00	120.00 14,972.00 190.00 340.00 4,600.00 240.00 20,462.00	499.00 14,950.00 450.00 499.00 13,950.00 450.00 30,798.00	
	Babcock Potable Water Elevated Storage Tank						
4	2.5 MG, 104 Feet Diam.; 160 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 2,175.00 200.00 3,635.00	500.00 1,000.00 50.00 2,000.00 2,500.00 250.00 6,300.00	120.00 10,630.00 140.00 315.00 1,400.00 140.00 12,745.00	499.00 5,899.00 450.00 499.00 2,999.00 450.00 10,796.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
	Broadview Potable Water Ground Storage Tank						T T 70.
5	4.5 MG, 138 Feet Diam.; 42.5 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 4,400.00 200.00 5,860.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00 6.600.00	120.00 10,242.00 140.00 315.00 1,400.00 140.00 12,357.00	499.00 8,199.00 450.00 499.00 7,599.00 450.00	BID NO ADDENDUM N
	Brackenridge (Ave B) Reuse Water Ground Storage Tank		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	.,	,	,,	
	0.4 MG, 54 Feet Diam.; 28.0 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 1,500.00 200.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00	120.00 4,181.00 140.00 290.00 1,150.00 115.00	575.00 4,899.00 450.00 575.00 4,199.00	
6	TOTAL		2,960.00	4,550.00	5,996.00	11,148.00	

F281-629	(Rev. 5/92)	15-5078	•	ı	ı	,	•
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	ons, LLC thara Ave., Ste. #208 NV 89117	lg, Inc. urt Rd. TX 75442	ervices :X 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan Under LLC P.O. Box 2591 Concroe, TX 7	H20 Solutions, LLC 9030 W. Sahara Ave. Las Vegas, NV 8911'	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy # San Antonio, TX 78258
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	1	<u> </u>	нел	H H H	FIR	дάς
	Brooks Reuse Water Ground Storage Tank						
	0.5 MG, 54 Feet Diam.; 27 Feet Overall Height		260.00	250.00	120.00	575.00	
	Inspection Cost Drained Drained Cleaning cost		360.00 500.00	250.00 1,000.00	120.00 6,131.00	575.00 4,999.00	
	Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation		300.00	50.00	140.00	450.00	
	Inspection Cost In-service (not-drained).		400.00	1,000.00	290.00	575.00	
	Cleaning Cost In-service (not-drained).		1,850.00	2,000.00	1,300.00	4,299.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
	Sedimentation Transport fees		2,500.00	1,900.00	1,900.00	1,000.00	
7	TOTAL		5,810.00	6,450.00	10,021.00	12,348.00	
'	Callaghan Potable Water Elevated Storage Tank						
	1.0 MG, 91.3 Feet Diam.; 39 Feet Bowl Height; 112.5 Feet Overall Height						
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	4,700.00	4,699.00	
	Drained Cleaning cost per additional 1" of sedimentation			50.00	140.00	450.00	
	Inspection Cost In-service (not-drained).		400.00	2,000.00	315.00	499.00	A
	Cleaning Cost In-service (not-drained).		1,850.00	2,500.00	1,400.00	2,299.00	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
0	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	ΩÖ
8	TOTAL		3,310.00	6,300.00	6,815.00	8,896.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
	Coliseum Reuse Water Elevated Storage Tank						TLA
	0.5 MG, 75 Feet Diam.; 43 Feet Bowl Height; 140 Feet Overall Height Inspection Cost Drained		360.00	500.00	120.00	575.00	BC NG
	Drained Cleaning cost		500.00	1,000.00	8,000.00	5,299.00	TA
	Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation		300.00	50.00	140.00	450.00	OT NC
	Inspection Cost In-service (not-drained).		400.00	2,000.00	315.00	575.00	žΣ
	Cleaning Cost In-service (not-drained).		1,750.00	2,500.00	1,400.00	4,299.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
9	TOTAL		3,210.00	6,300.00	10,115.00	11,648.00	DD
	Dos-Rios Water Hydro-Pneumatic Tank						<
	20 K; 10 Feet Diam.; 6.5 Feet Water Level Tank; 40 Feet Length						
	Inspection Cost Drained		250.00	500.00	120.00	425.00	
	Drained Cleaning cost per additional 1" of sedimentation		100.00	500.00	50.00	450.00	
10	Drained Cleaning Cost Out Of Service		1,000.00 1,350.00	2,000.00	1,200.00	1,850.00	
10	TOTAL Final anish through Planta Water Flavored Starrage Toult		1,350.00	3,000.00	1,370.00	2,725.00	
	Fredericksburg Reuse Water Elevated Storage Tank 1.0 MG, 74 Feet Diam.; 38 Feet Bowl Height; 135 Feet Overall Height						
	Inspection Cost Drained		360.00	500.00	120.00	575.00	
	Drained Cleaning cost		500.00	1,000.00	4,700.00	8,499.00	
	Drained Cleaning cost per additional 1" of sedimentation		200.00	50.00	140.00	450.00	
	Inspection Cost In-service (not-drained).		400.00	2,000.00	315.00	575.00	
	Cleaning Cost In-service (not-drained).		1,975.00	2,500.00	1,400.00	5,250.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
	Sedimentation Transport fees		2,500.00	1,900.00	2,000.00	1,000.00	
11	TOTAL		5,935.00	8,200.00	8,815.00	16,799.00	

F281-629	(Rev. 5/92)	15-5078				ı	•
FOR:	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Fexas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
TIME & DATE:	3:00 p.m., February 25, 2015		Marcan U LLC P.O. Box Concroe,	20 So 30 W 1s Veg	nylor'c 52 Lo rrmer	exas T 13 Sta hiteh	r Chri 1659 S In An
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		M. L.L P.C	H2 90 La	Ta 11 Fa	Te 10 W]	EJ C 2065 San
	Salado Potable Water Ground Storage Tank 5 MG, 172.0 Feet Diam.; 30.5 Feet Overall Height; Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained).		360.00 500.00 400.00 5,600.00	500.00 1,000.00 100.00 2,000.00 2,500.00	120.00 11,910.00 190.00 315.00 2,700.00	499.00 8,599.00 450.00 499.00 7,665.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
13	TOTAL South Foster Potable Water Storage Tank 2.0 MG, 100 Feet Diam.; 40 Feet Bowl Height; 164.5 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL Stotzer Reuse Water Ground Storage Tank		7,060.00 360.00 500.00 400.00 4,300.00 200.00 5,760.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	15,375.00 120.00 6,192.00 190.00 315.00 2,700.00 140.00 9,657.00	499.00 5,299.00 450.00 499.00 2,699.00 450.00 9,896.00	BID NOT TABULATED ADUM NO. 2 NOT RETURNED
14	2.2 MG, 84.0 Feet Diam.; 51.0 Feet Overall Height; Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees		360.00 500.00 400.00 2,475.00 200.00 2,500.00	500.00 1,000.00 100.00 2,000.00 2,500.00 250.00 1,900.00	120.00 10,524.00 140.00 290.00 1,400.00 1,500.00	575.00 9,799.00 450.00 575.00 5,799.00 450.00 1,000.00	BID NOT T ADDENDUM NO.
14	TOTAL Turtle Creek #1 Potable Water Ground Storage Tank No. 1		6,435.00	8,250.00	14,114.00	18,648.00	
15	O.5 MG, 52 Feet Diam.; 32 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 1,675.00 200.00 3,135.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	120.00 5,500.00 140.00 290.00 1,300.00 140.00 7,490.00	499.00 3,699.00 450.00 499.00 1,999.00 450.00 7,596.00	
10	TOTAL TOTAL	1	3,133.00	7,000.00	7,470.00	7,070.00	

F281-629	(Rev. 5/92)	15-5078					
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	, LLC ra Ave., Ste. #208 / 89117	lg, Inc. urt Rd. FX 75442	Services r. , TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
PROPOSAL FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan Underwater LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	Chris Conti 1659 Stone C m Antonio, '
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		ZIÄÖ	Ľ S H	Te 111 Fa	Te 10	EJ 20 Sa
	Turtle Creek #2 Potable Water Ground Storage Tank No. 2 0.5 MG, 52 Feet Diam.; 32 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained)		360.00 500.00 400.00 1,675.00	250.00 1,000.00 50.00 1,000.00 2,000.00	120.00 5,500.00 140.00 290.00 1,300.00	499.00 3,699.00 450.00 499.00 1,999.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
16	TOTAL		3,135.00	4,550.00	7,490.00	7,596.00	
	Wurzbach Potable Water Ground Storage Tank No. 1 7.5 MG, 181 Feet Diam.; 40 Feet Overall Height Inspection Cost Drained Drained Cleaning cost		360.00 500.00	500.00 1,000.00	120.00 10,472.00	499.00 13,950.00	
	Drained Cleaning cost per additional 1" of sedimentation			100.00	190.00	450.00	
	Inspection Cost In-service (not-drained)		400.00	2,000.00	340.00	499.00	
	Cleaning Cost In-service (not-drained)		7,125.00	2,500.00	3,800.00	11,950.00	
47	Underwater Cleaning cost per additional 1" of sedimentation		200.00	500.00	140.00	450.00	臣
17	TOTAL	-	8,585.00	6,600.00	15,062.00	27,798.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
	Wuzbach Potabl Water Ground Storage Tank No. 2						BID NOT TABULATED NDUM NO. 2 NOT RETU
	7.5 MG, 181 Feet Diam.; 40 Feet Overall Height Inspection Cost Drained		360.00	500.00	120.00	499.00	LAT R. A.T
	Drained Cleaning cost		500.00	1,000.00	10,472.00	13,950.00	100
	Drained Cleaning cost per additional 1" of sedimentation		500.00	100.00	190.00	450.00	Z N
	Inspection Cost In-service (not-drained)		400.00	2,000.00	340.00	499.00	17.7 .0
	Cleaning Cost In-service (not-drained)		7,125.00	2,500.00	3,800.00	11,950.00	S Z
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	500.00	140.00	450.00	<u> </u>
18	TOTAL		8,585.00	6,600.00	15,062.00	27,798.00	B E
	General McMullen Potable Water Elevated Storage Tank						<u>[</u>
	0.25 MG, 40 Feet Diam.; 136 Feet Overall Height		2 40 00	7 00.00	420.00	400.00	₹
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	7,000.00	3,899.00	
	Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained).		400.00	50.00 2,000.00	140.00 280.00	450.00 499.00	
	Cleaning Cost In-service (not-drained).		1,250.00	2,500.00	1,150.00	1,999.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
19	TOTAL		2,710.00	6,300.00	8,830.00	7,796.00	
	Golden Potable Water Ground Storage Tank		ĺ	ĺ	Í	Í	
	12.5 MG, 226 Feet Diam.; 50 Feet Overall Height						
	Inspection Cost Drained		360.00	500.00	140.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	16,972.00	22,950.00	
	Drained Cleaning cost per additional 1" of sedimentation			100.00	265.00	450.00	
	Inspection Cost In-service (not-drained).		400.00	2,000.00	390.00	499.00	
	Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation		9,150.00 200.00	2,500.00 500.00	3,700.00 165.00	15,950.00 450.00	
20	TOTAL		10,610.00	6,600.00	21,632.00	40,798.00	
20	TOTAL		10,010.00	0,000.00	41,034.00	70,770.00	

F281-62	9 (Rev. 5/92)	15-5078		ı	ı	ı	Î
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		ater Services,	LLC Ave., Ste. #208 89117	, Inc. t Rd. X 75442	Services r. TX 75791	cting, Inc. k Pkwy #804 K 78258
FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 754	Fexas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
ПЕМ NO.	DESCRIPTION AND APPROXIMATE QUANTITY	1	Z J J Č	н Ж й	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Ţ ï ≱	S. 2. E.
21	Hutcins Potable Water Elevated Storage Tank 0.5 MG, 50 Feet Diam.; 159 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 1,400.00 200.00 2,860.00	500.00 1,000.00 50.00 2,000.00 2,500.00 250.00 6,300.00	120.00 8,000.00 140.00 280.00 1,000.00 140.00 9,680.00	499.00 3,999.00 450.00 499.00 2,199.00 450.00 8,096.00	
	King Potable Water Ground Storage Tank 0.5 MG, 52 Feet Diam.; 34 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 1,525.00 200.00	250.00 1,000.00 30.00 1,000.00 2,000.00 250.00	120.00 65,000.00 140.00 280.00 1,000.00 140.00	499.00 3,699.00 450.00 499.00 1,999.00 450.00	ABULATED 2 NOT RETURNED
22	TOTAL La Rosa Potable Water Ground Storage Tank 3 MG, 122 Feet Diam.; 34 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		2,985.00 360.00 500.00 400.00 2,925.00 200.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00	120.00 9,242.00 140.00 315.00 1,500.00 140.00	7,596.00 499.00 7,299.00 450.00 499.00 4,599.00 450.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETU
23	TOTAL Somerset Potable Water Ground Storage Tank 0.3 MG, 40 Feet Diam.; 32 Feet overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		4,385.00 360.00 500.00 400.00 1,375.00 200.00 2,835.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	11,457.00 120.00 5,831.00 140.00 280.00 1,000.00 140.00 7,511.00	499.00 3,699.00 450.00 499.00 1,799.00 450.00 7,396.00	

F281-629	(Rev. 5/92)	15-5078	i i	ī	ı	ı	i
PROPOSAL FOR:	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
TIME & DATE:	(March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan U LLC P.O. Box Concroe,	0 Sol 80 W.: Veg	/lor'd 52 Le mers	tas Ta 3 Stac iiteho	Chris 559 S
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		Marc LLC P.O. J Conc	H2 903 Las	Tay 111	Te ₂	EJ 206 Sar
	Vestal Potable Water Elevated Storage Tank		,,,,,,	,,,,,,	. , ,	,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	1.5 MG, 91 Feet Diam.; 162 Feet Overall Height						
	Inspection Cost Drained		360.00	500.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	9,630.00	4,899.00	
	Drained Cleaning cost per additional 1" of sedimentation			50.00	140.00	450.00	
	Inspection Cost In-service (not-drained)		400.00	2,000.00	315.00	499.00	
	Cleaning Cost In-service (not-drained)		1,875.00	2,500.00	1,400.00	2,499.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
25	TOTAL		3,335.00	6,300.00	11,745.00	9,296.00	
	Wild Turkey Potable Water Ground Storage Tank		,	,	ŕ	,	
	0.5 MG, 55 Feet Diam.; 32 Feet Overall Height						
	Inspection Cost Drained		360.00	250.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	6,131.00	3,999.00	
	Drained Cleaning cost per additional 1" of sedimentation			50.00	150.00	450.00	Ω
	Inspection Cost In-service (not-drained)		400.00	1,000.00	315.00	499.00	Ä
	Cleaning Cost In-service (not-drained)		1,725.00	2,000.00	1,000.00	2,199.00	2 E
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	150.00	450.00	
26	TOTAL		3,185.00	4,550.00	7,866.00	8,096.00	AT RI
	Minor Repair (Item F)						BID NOT TABULATED IDUM NO. 2 NOT RETI
			250.00	50.00	235.00	350.00	AB N
27	Hourly Rate for 40 Hours		10,000.00	2,000.00	9,400.00	14,000.00	J. T.
	Emergency Services (Item E)			250.00	500.00	1,150.00	5 Ž
	Mobilization 4 each			1,000.00	2,000.00	4,600.00	Z Z
			250.00	50.00	150.00	450.00	
28	Hourly Rate for 60 Hours		15,000.00	3,000.00	9,000.00	27,000.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
							DI
							▼
	TOTAL			4,000.00	11,000.00	31,600.00	
	TOTAL AMOUNT FOR VEAD 2017 (TEEM 1 20)		157.050.00	160 590 00	272 840 00	424 779 00	
	TOTAL AMOUNT FOR YEAR 2016 (ITEM 1-28) Artesia Potable Water Ground Storage Tank		157,050.00	160,580.00	373,849.00	434,778.00	
	S S S S S S S S S S S S S S S S S S S						
	5 MG; 164.5 Feet Diam.; 42.3 Feet Overall Height Inspection Cost Drained		360.00	500.00	120.00	499.00	
	*		500.00	1,000.00	11,000.00	8,599.00	
	Drained Cleaning cost		300.00	1,000.00	140.00	8,399.00 450.00	
	Drained Cleaning cost per additional 1" of sedimentation		400.00				
	Inspection Cost In-service (not-drained)		400.00	2,000.00	315.00	499.00	
	Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		4,950.00	2,500.00	1,400.00 140.00	7,665.00 450.00	
1	Underwater Cleaning cost per additional 1" of sedimentation		200.00 6,410.00	500.00 6,600.00			
<u>1.</u>	TOTAL	ļ	0,410.00	0,000.00	13,115.00	18,162.00	

,	v. 3/92)	15-5076	ĺ		Í	Î	i
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
PROPOSAL An	nnual Contract for Potable and Reuse Water Storage Tank Cleaning		erw 91	ns, I	ing Bur , T.	Ser r. TX	Oa , T.
	d Inspection		Marcan Under LLC P.O. Box 2591 Concroe, TX 7	tior Sah S, N	Div ter] ille	Texas Tank S 103 Stacy Dr. Whitehouse, ⁷	Cor
TIME & (M	larch 1, 2015 through December 31, 2015		n L	olu W. P	rsv.	Tar acy hou	Sto nto
DATE: 3:0	00 p.m., February 25, 2015		rca C O. B	0 S 30 V 8 V	ylor 52 I	Texas Tank 103 Stacy D Whitehouse,	Chi 559
ITEM NO. DES	CRIPTION AND APPROXIMATE QUANTITY		Marc LLC P.O. Conc	H2 900 Las	Tay 11: Far	Te: 100	EJ 200 Sar
Co	oncept Therapy Potable Water Concrete Standpipe No. 1						
0.0	03 MG; 10 feet diam.; 36 Feet Overall Height						
Ins	spection Cost Drained		360.00	250.00	120.00	499.00	
Dr	rained Cleaning cost		500.00	1,000.00	3,524.00	2,150.00	
Dr	rained Cleaning cost per additional 1" of sedimentation			50.00	75.00	450.00	
Ins	spection Cost In-service (not-drained)		400.00	1,000.00	290.00	499.00	
Cle	eaning Cost In-service (not-drained)		850.00	2,000.00	1,300.00	1,650.00	
	nderwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
	OTAL		2,310.00	4,550.00	5,449.00	5,698.00	
	oncept Therapy Potable Water Concrete Standpipe No. 2		,	,	,	,	
	03 MG; 10 Feet Diam.; 36 Feet Overall Height						
Ins	spection Cost Drained		360.00	250.00	120.00	499.00	
Dr	rained Cleaning cost		500.00	1,000.00	3,524.00	2,150.00	
Dr	rained Cleaning cost per additional 1" of sedimentation			50.00	75.00	450.00	
Ins	spection Cost In-service (not-drained)		400.00	1,000.00	290.00	499.00	
Cle	eaning Cost In-service (not-drained)		850.00	2,000.00	1,300.00	1,650.00	
Un	nderwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	ED
3 TO	OTAL		2,310.00	4,550.00	5,449.00	5,698.00	N. N.
	oncept Therapy Potable Water Concrete Standpipe No. 3		ĺ	ĺ	ŕ	ĺ	ABULATED 2 NOT RETURNED
	03 MG; 10 Feet Diam.; 36 Feet Overall Heith						E E
	spection Cost Drained		360.00	250.00	120.00	499.00	T.
Dr	rained Cleaning cost		500.00	1,000.00	3,524.00	2,150.00	BU
Dr	rained Cleaning cost per additional 1" of sedimentation			50.00	75.00	450.00	1. 2
Ins	spection Cost In-service (not-drained)		400.00	1,000.00	290.00	499.00	7. O
Cle	eaning Cost In-service (not-drained)		850.00	2,000.00	1,300.00	1,650.00	N N N
Un	nderwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	BID NOT TABULATED NDUM NO. 2 NOT RETI
	OTAL		2,310.00	4,550.00	5,449.00	5,698.00	B Z
	oncept Therapy Potable Water Hydro-Pneumatic Tank 0.01 MG; 6.0 Feet (AM.; 24 INCHES WATER/LEVEL TANK; 6.0 FEET LENGTH						BID NOT 1 ADDENDUM NO.
Ins	spection Cost Drained		360.00	250.00	120.00	425.00	,
Dr	rained Cleaning cost		500.00	1,000.00	1,200.00	1,850.00	
Dr	rained Cleaning cost per additional 1" of sedimentation			50.00	75.00	450.00	
Ins	spection Cost In-service (not-drained)		400.00	1,000.00	100.00		
	eaning Cost In-service (not-drained)		800.00	2,000.00	700.00		
	nderwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	75.00		
5 TO	OTAL		2,260.00	4,550.00	2,270.00	2,725.00	
	evine Reuse Water Elevated Storage Tank						
	2 MG; 84 Feet Diam.; 43 Feet Bowl Height; 83 Feet Overall Height						
	spection Cost Drained		360.00	500.00	120.00	575.00	
	rained Cleaning cost		500.00	1,000.00	7,630.00	10,250.00	
	rained Cleaning cost per additional 1" of sedimentation			50.00	140.00	450.00	
	spection Cost In-service (not-drained)		400.00	2,000.00	1,400.00	575.00	
	eaning Cost In-service (not-drained)		1,975.00	2,500.00	315.00	4,950.00	
	nderwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
	OTAL		3,435.00	6,300.00	9,745.00	17,250.00	

1 201-02)	(Rev. 5/92)	15-5078	ĺ	. 1	1	Í	Ì
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
PROPOSAL	Annual Contract for Potable and Reuse Water Storage Tank Cleaning		erv 91	ns, nara NV	ing Bu T, T	Sei T.	of T.
FOR:	and Inspection		Jnd 255	tion Sah S, N	Div ter ille	nk ' Dj	Cor
TIME &	(March 1, 2015 through December 31, 2015		n L	olu W. ega	vs.r	Tai acy hou	Sto nto
DATE:	3:00 p.m., February 25, 2015		Marcan Under LLC P.O. Box 2591 Concroe, TX 7	0 S 30 V	/lor 52 I me	Texas Tank S 103 Stacy Dr. Whitehouse, ⁷	Chr 559
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		Marc LLLC P.O. Conc	H2 903 Las	Тау 115 Far	Tes 103 Wh	EJ (2006
	East Houston Reuse Water Ground Storage Tank		,,,,,,	, , , , ,	. , ,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	1.0 MG; 75 Feet Diam.; 32 Feet Overall Height						
	Inspection Cost Drained		360.00	500.00	120.00	575.00	
	Drained Cleaning cost		500.00	1,000.00	4,700.00	8,199.00	
	Drained Cleaning cost per additional 1" of sedimentation			100.00	140.00	450.00	
	Inspection Cost In-service (not-drained).		400.00	2,000.00	315.00	575.00	
	Cleaning Cost In-service (not-drained).		1,925.00	2,500.00	1,400.00	5,250.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	500.00	140.00	450.00	
7	TOTAL		3,385.00	6,600.00	6,815.00	15,499.00	
<u> </u>	General McMullen Potable Water Elevated Storage Tank		2,202100	0,000100	0,022100	20,155100	
	2 MG; 95 Feet Diam.; 45 Feet Bowl Height; 135 Feet Overall Height						
	Inspection Cost Drained		360.00	250.00	120.00	499.00	
	Drained Cleaning cost		500.00	1,000.00	9,630.00	5,299.00	
	Drained Cleaning cost per additional 1" of sedimentation		300.00	50.00	140.00	450.00	
	Inspection Cost In-service (not-drained).		400.00	1,000.00	315.00	499.00	
	Cleaning Cost In-service (not-drained).		2,075.00	2,000.00	1,400.00	2,699.00	
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	Д
8	TOTAL		3,535.00	4,550.00	11,745.00	9,896.00	Ë
	Helotes/Adobe Ranch Potable Water Ground Storage Tank		3,555.00	4,550.00	11,745.00	2,020.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
	5 MG; 150 Feet Diam.; 41.8 Feet Overall Height						BID NOT TABULATED IDUM NO. 2 NOT RETU
	Inspection Cost Drained		360.00	250.00	120.00	499.00	,A]
	Drained Cleaning cost		500.00	1,000.00	11,800.00	8,599.00	5 5
	Drained Cleaning cost per additional 1" of sedimentation		300.00	50.00	190.00	450.00	AB 2 N
	Inspection Cost In-service (not-drained)		400.00	1,000.00	315.00	499.00	7 T.
	Cleaning Cost In-service (not-drained)		5,250.00	2,000.00	2,000.00	7,665.00	<u>5</u> Ż
	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	ZZ
9	TOTAL		6,710.00	4,550.00	14,565.00	18,162.00	
3	Helotes Park #3 Potable Water Standpipe		0,710.00	4,550.00	14,505.00	10,102.00	鱼
	0.27 MG; 21.5 Feet Diam.; 100 Feet Overall Height						DC
	Inspection Cost Drained		360.00	500.00	120.00	499.00	<
	Drained Cleaning cost		500.00	1,000.00	4,400.00	2,150.00	
	Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation		500.00	50.00	90.00	450.00	
	Inspection Cost In-service (not-drained)		400.00	2,000.00	340.00	499.00	
			1,825.00	2,500.00	1,400.00		
	Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	90.00	1,850.00 450.00	
10							
10	TOTAL Hills Detable Water Crown Stores Tork		3,285.00	6,300.00	6,440.00	5,898.00	
	Hills Potable Water Ground Storage Tank						
	3 MG; 90 Feet Diam.; 64 Feet Overall Height Inspection Cost Drained		260.00	250.00	120.00	499.00	
	1 1		360.00 500.00	1,000.00	120.00 9,242.00		
	Drained Cleaning cost		500.00			7,299.00	
	Drained Cleaning cost per additional 1" of sedimentation		400.00	50.00	140.00	450.00	
	Inspection Cost In-service (not-drained)		400.00	1,000.00	315.00	499.00	
	Cleaning Cost In-service (not-drained)		2,875.00	2,000.00	1,400.00	4,599.00	
4.4	Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
11	TOTAL		4,335.00	4,550.00	11,357.00	13,796.00	

F281-629 (Rev. 5/92)	15-5078					
SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		vater Services,	LLC a Ave., Ste. #208 89117	g, Inc. rrt Rd. X 75442	rvices X 75791	acting, Inc. ak Pkwy #804 X 78258
PROPOSAL Annual Contract for Potable and Reuse Water Storage Tank Cleaning FOR: and Inspection TIME & (March 1, 2015 through December 31, 2015 DATE: 3:00 p.m., February 25, 2015 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burr Rd. Farmersville, TX 754	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
Judson Potable Water Elevated Storage Tank				-	-	
0.5 MG; 40 Feet Diam.; 139.5 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained)		360.00 500.00 400.00 1,825.00	500.00 1,000.00 100.00 2,000.00 2,500.00	120.00 8,000.00 140.00 315.00 1,300.00	499.00 3,999.00 450.00 499.00 2,199.00	
Underwater Cleaning cost per additional 1" of sedimentation		200.00	500.00	140.00	450.00	
12. TOTAL		3,285.00	6,600.00	10,015.00	8,096.00	
Marshall Potable Water Ground Storage Tank 0.55 MG; 55 Feet Diam.; 32 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 1,800.00 200.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00	120.00 6,131.00 140.00 290.00 1,300.00 140.00	499.00 3,699.00 450.00 499.00 1,999.00 450.00	ED
13 TOTAL		3,260.00	6,600.00	8,121.00	7,596.00	RN
Naco Potable Water Ground Storage Tank 7.5 MG; 165 Feet Diam.; 52.2 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 7,000.00 200.00 8,460.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	120.00 10,472.00 140.00 340.00 1,500.00 140.00 12,712.00	499.00 13,950.00 450.00 499.00 11,950.00 450.00 27,798.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
Pearsall Reuse Water Ground Storage Tank		,	,	,	,	DE
2.5 MG; 120 Feet Diam.; 33 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 2,525.00 200.00 3,985.00	500.00 1,000.00 100.00 2,000.00 2,500.00 500.00 6,600.00	120.00 7,500.00 165.00 315.00 1,500.00 165.00 9,765.00	575.00 10,999.00 450.00 575.00 5,999.00 450.00 19,048.00	AD
Pinn Rd. Reuse Water Ground Storage Tank		3,5 32.30	2,000.00	2,7.02.00	_>,0.0.00	
3 MG; 84 Feet Diam.; 80 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained)		360.00 500.00 400.00 2,825.00	250.00 1,000.00 50.00 1,000.00 2,000.00	120.00 9,000.00 140.00 315.00 1,400.00	575.00 12,450.00 450.00 575.00 9,350.00	
Underwater Cleaning cost per additional 1" of sedimentation		200.00	250.00	140.00	450.00	
16 TOTAL		4,285.00	4,550.00	11,115.00	23,850.00	

F281-629	(Rev. 5/92)	15-5078					
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	LLC a Ave., Ste. #208 : 89117	g, Inc. urt Rd. 'X 75442	rvices X 75791	acting, Inc. ak Pkwy #804 'X 78258
PROPOSAL FOR: TIME & DATE: ITEM NO.	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015 DESCRIPTION AND APPROXIMATE QUANTITY		Marcan Underwater LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 754	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
	Randolph Potable Water Ground Storage Tank 5 MG; 165 Feet Diam.; 32 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 5,025.00	250.00 1,000.00 50.00 1,000.00 2,000.00	120.00 11,910.00 140.00 340.00 1,550.00	499.00 8,599.00 450.00 499.00 7,665.00	
17	Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 6,485.00	250.00 4,550.00	140.00 14,200.00	450.00 18,162.00	
	Seale Potable Water Ground Storage Tank No. 2 3 MG; 90 Feet Diam.; 64.5 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 3,000.00 200.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00	120.00 9,242.00 140.00 315.00 1,400.00 140.00	499.00 8,199.00 450.00 499.00 4,699.00 450.00	(ED
18	TOTAL		4,460.00	4,550.00	11,357.00	14,796.00	JR.
19	Winwood Potable Water Ground Storage Tank 2 MG; 84 Feet Diam; 48 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 2,375.00 200.00 3,835.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	120.00 8,192.00 140.00 290.00 1,400.00 140.00 10,282.00	499.00 4,999.00 450.00 499.00 2,650.00 450.00 9,547.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
	Winwood Potable Water Hydro-Pneumatic Storage Tank 3 MG; 10 Feet Diam.; 7 Feet Overall Height; 36 Feet Length Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 1,800.00 200.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00	120.00 1,200.00 90.00 550.00 950.00 90.00	425.00 1,850.00 450.00	ADDEN
20	TOTAL Anaqua Springs Potable Water Ground Storage Tank 1		3,260.00	4,550.00	3,000.00	2,725.00	
	0.06 MG; 26 Feet Diam.; 16 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 1,300.00 200.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00	120.00 3,719.00 90.00 280.00 1,000.00 90.00	499.00 1,650.00 450.00 499.00 1,650.00 450.00	
21	TOTAL		2,760.00	4,550.00	5,299.00	5,198.00	

F281-629	9 (Rev. 5/92)	15-5078					
PROPOSAI	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning		Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	ıs, LLC ara Ave., Ste. #208 tV 89117	ing, Inc. Burt Rd. , TX 75442	Fexas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
FOR: TIME & DATE:	and Inspection (March 1, 2015 through December 31, 2015 3:00 p.m., February 25, 2015		Marcan Underwater LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd Farmersville, TX 75	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 757	EJ Chris Contracti 20659 Stone Oak I San Antonio, TX 7
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		C P.C	H2 90 La	Та 11 Fа	Te 10 W	EJ 20 Sa
<u>22</u>	Anaqua Springs Potable Water Ground Storage Tank 2 0.06 MG; 26 Feet Diam.; 16 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		360.00 500.00 400.00 1,300.00 200.00 2,760.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	120.00 3,719.00 90.00 280.00 1,000.00 90.00 5,299.00	499.00 1,650.00 450.00 499.00 1,650.00 450.00 5,198.00	
	Anaqua Springs Potable Water Ground Storage Tank 3 0.06 MG; 26 Feet Diam.; 16 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		360.00 500.00 400.00 1,300.00 200.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00	120.00 3,719.00 90.00 280.00 1,000.00 90.00	499.00 1,650.00 450.00 499.00 1,650.00 450.00	ABULATED 2 NOT RETURNED
23	Anaqua Springs Potable Water Ground Storage Tank 4 0.06 MG; 26 Feet Diam.; 16 Feet Overall Height Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation		2,760.00 360.00 500.00 400.00 1,300.00 200.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00	5,299.00 120.00 3,719.00 90.00 280.00 1,000.00 90.00	5,198.00 499.00 1,650.00 450.00 499.00 1,650.00 450.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETU
<u>24</u> <u>25</u>	Cagnon Potable Water Ground Storage Tank 1.0 MG; 74.0 Feet Diam.; 34.0 Feet Water Level Tank Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		2,760.00 360.00 500.00 400.00 1,700.00 200.00 3,160.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00	5,299.00 120.00 8,000.00 140.00 315.00 1,400.00 140.00 10,115.00	5,198.00 499.00 3,699.00 450.00 499.00 2,250.00 450.00 7,847.00	

PROPOSAL Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection TIME & (March 1, 2015 through December 31, 2015 DATE: 3:00 p.m., February 25, 2015 TEM NO. DESCRIPTION AND APPROXIMATE QUANTITY	Marcan Underwater Services, LLC P.O. Box 2591 Concroe, TX 77305	H20 Solutions, LLC 9030 W. Sahara Ave., Ste. #208 Las Vegas, NV 89117	Taylor'd Diving, Inc. 1152 Lester Burt Rd. Farmersville, TX 75442	Texas Tank Services 103 Stacy Dr. Whitehouse, TX 75791	EJ Chris Contracting, Inc. 20659 Stone Oak Pkwy #804 San Antonio, TX 78258
Cagnon Potable Water Ground Storage Tank 1.0 MG; 64.0 Feet Diam.; 168 Feet Water Level Tank Inspection Cost Drained Drained Cleaning cost Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL Minor Repairs (Item F) Hourly Rate for 40 hours TOTAL Emergency Services (Item E) 4 ea. Mobilation 60 hours., Hourly Rate TOTAL TOTAL	360.00 500.00 400.00 1,700.00 200.00 3,160.00 250.00 10,000.00	250.00 1,000.00 50.00 1,000.00 2,000.00 250.00 4,550.00 2,000.00 250.00 1,000.00 50.00 3,000.00	120.00 9,630.00 140.00 315.00 1,400.00 140.00 11,745.00 235.00 9,400.00 500.00 2,000.00 150.00 9,000.00	499.00 4,499.00 450.00 499.00 2,499.00 450.00 8,896.00 14,000.00 4,600.00 450.00 27,000.00	BID NOT TABULATED ADDENDUM NO. 2 NOT RETURNED
TOTAL TOTAL AMOUNT FOR YEAR 2017 (ITEMS 1-28)	123,960.00	4,000.00	11,000.00 246,422.00	31,600.00	AI
Terms *LOW BIDDER	3% 7 days	5% 15 days	2% 10 days	1% 20 days	

BID INVITATIONS WERE E-MAILED TO AND/OR PICKED UP BY:

Affinity Diving Services
American Underwater Services
Clean Harbors
EJ Chris Contracting, Inc.
H2O Solutions

Hydro-Klean Liquid Engineering Marcan Underwater Services Tank Industry Taylor'd Diving Inc. Texas Tank Services US Underwater Services Utility Service Demandstar SAWS Website