F281-629	(Rev. 5/92) 13	3-5078			
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	ervices 55 S 03	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
PROPOSAL FOR: TIME & DATE:	Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Undera Inc. P.O. Box 126216 Ft Worth, TX 761	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineerin 7 East Airport Rd. Billings, MT 5910
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		Ameı Inc. P.O. Ft W,	Te. 129 Ty	Lic 7 H Bil
<u>1.</u>	ASR Clearwell No. 1 Potable Water Tank 3.0 MG; 179 feet diam.; 16.7 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 125.00 2,330.00	499.00 N/A 499.00 6,250.00 250.00 7,498.00	
2.	Austin Potable Water Elevated Storage Tank 1.5 MG; 88 feet diam.; 138 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,400.00 125.00 2,230.00	499.00 N/A 499.00 2,250.00 250.00 3,498.00	
<u>3.</u>	Avenue B (Brackenridge) Reuse Water Ground Storage Tank 0.4 MG; 54 feet diam.; 28 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 300.00 1,250.00 125.00 4,000.00 6,055.00	499.00 N/A 499.00 1,750.00 250.00 650.00 3,648.00	NO BID
4.	Bitters Potable Water Hydro-Pneumatic Tank 0.025 MG; 10 feet diam.; 45 feet length Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Rained Cleaning Cost out of Service TOTAL		230.00 150.00 450.00 830.00	299.00 125.00 995.00 1,419.00	
5.	Bitters Potable Water Ground Storage Tank 5 MG; 165.0 feet diam.; 33.0 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,650.00 200.00 2,555.00	499.00 N/A 499.00 8,400.00 250.00 9,648.00	

F281-629 (Rev. 5/9	/92)	13-5078			
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		ater Services, 6 5126	rices S	ing, Corp. d. 108-0230
FOR: Potat	ual Contract for ble and Reuse Water Storage Tank Cleaning and Inspection uary 1, 2014 through December 31, 2014) p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
Brook 0.5 M Inspec Draine Inspec Cleani Under	PTION AND APPROXIMATE QUANTITY ks Reuse Water Ground Storage Tank IG; 54 feet diam.; 27 feet overall height action Cost Drained ted Cleaning cost per additional 1" of sedimentation action Cost In-service (not drained) ting Cost In-service (no drained) browater Cleaning cost per additional 1" of sedimentation nentation Transport fees AL.		Щ <u>Э</u> <u>О</u> <u>й</u> 230.00 150.00 300.00 1,400.00 150.00 2,000.00 4,230.00	499.00 N/A 499.00 2,250.00 250.00 850.00 4,348.00	Li Bi
Colise 0.5 M Inspec Draine Inspec Cleani Under	Beum Reuse Water Elevated Storage Tank IG ; 75 feet diam. ; 43 feet bowl height ; 140 feet overall height action Cost Drained bed Cleaning cost per additional 1" of sedimentation action Cost In-service (not drained) bring Cost In-service (not drained) brwater Cleaning cost per additional 1" of sedimentation brwater Cleaning cost per additional 1" of sedimentation brwater Cleaning cost per additional 1" of sedimentation		4,230.00 230.00 150.00 325.00 1,400.00 150.00 2,150.00 4,405.00	499.00 N/A 499.00 2,150.00 250.00 850.00 4,248.00	
0.06 M Inspec Draine Inspec Cleani Under 8. TOTA			175.00 100.00 289.00 1,100.00 150.00 1,814.00	499.00 N/A 499.00 1,050.00 250.00 2,298.00	NO BID
0.004 Inspec Draine 9. TOTA Dos R	inion Potable Water Hydro-Pneumatic Tank MG; 6 feet diam.; 22 feet length action Cost Drained ned Cleaning cost per additional 1" of sedimentation ned Cleaning cost out of service AL Rios Reuse Water Hydro-pneumatic Tank MG; 10 feet diam; 6.5 feet Water Level Tank; 40 feet length		200.00 50.00 300.00 550.00	299.00 125.00 995.00 1,419.00	
Inspec Draine	action Cost Drained ned Cleaning cost per additional 1" of sedimentation ned Cleaning cost out of service		200.00 50.00 300.00 550.00	299.00 125.00 1,050.00 1,474.00	

F281-629	9 (Rev. 5/92)	13-5078		1	
PROPOSAI FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>11.</u>	Foster Potable Water Elevated Storage Tank 2.0 MG; 105 feet diam; 36 feet bowl height; 150+/- feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning cost per additional 1" of sedimentation Underwater Cleaning cost per additional 1" of sedimentation TOTAL Fredericksburg Reuse Water Elevated Storage Tank		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,650.00 250.00 3,898.00	
12.	1.0 MG; 74 feet diam.; 38 feet bowl height; 135 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,000.00 4,355.00	499.00 N/A 499.00 2,450.00 250.00 750.00 4,448.00	
13.	Grissom Potable Water Elevated Storage Tank 2.5 MG; 102 feet diam.; 49.6 feet bowl height; 185 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,850.00 250.00 4,098.00	NO BID
14.	Hildebrand Potable Water Elevated Storage Tank 2 MG; 95.0 feet diam.; 45 feet bowl height; 119 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,650.00 250.00 3,898.00	
15.	Indian Springs Potable Water Standpipe 3 MG; 64 feet diam.; 129 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 150.00 350.00 1,600.00 150.00 2,500.00	499.00 N/A 499.00 4,250.00 250.00 5,498.00	

F281-629) (Rev. 5/92)	13-5078			
FOR: TIME & DATE:	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>ITEM NO.</u>	DESCRIPTION AND APPROXIMATE QUANTITY Inwood Potable Water Ground Storage Tank 1.2 MG; 80 feet diam; 35 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost per additional 1" of sedimentation Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,400.00 150.00	499.00 N/A 499.00 2,950.00 250.00	B 7 L
<u>16.</u> 17.	TOTAL Stotzer Reuse Water Ground Storage Tank 2.2 MG, 84.0 feet diam.; 51.0 feet overall height; Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		2,255.00 230.00 150.00 325.00 1,400.00 150.00 2,000.00 4,255.00	4,198.00 499.00 N/A 499.00 6,750.00 250.00 2,150.00 10,148.00	NO BID
18.	Amhurst Potable Water Elevated Storage Tank 0.8 MG, 62 feet diam.; 110 feet overall height; Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,400.00 150.00 2,255.00	499.00 N/A 499.00 1,950.00 250.00 3,198.00	
19.	Bear Springs Potable Water Ground Storage Tank 0.28 MG, 32 feet diam.; 48 feet overall height; Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 150.00 289.00 1,100.00 150.00 1,889.00	499.00 N/A 499.00 1,250.00 250.00 2,498.00	

F281-629) (Rev. 5/92)	13-5078			
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>20.</u>	Echo Mountain Potable Water Elevated Storage Tank 2.5 MG, 105 feet diam.; 155 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,850.00 250.00 4,098.00	
21.	Fleetwood Potable Water Elevated Storage Tank 0.5 MG, 55 feet diam.; 84.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 300.00 1,400.00 150.00 2,230.00	499.00 N/A 499.00 1,650.00 250.00 2,898.00	
22.	Knights Cross Potable Water Ground Storage Tank 6 MG, 90 feet diam.; 128 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 150.00 325.00 1,500.00 150.00 2,375.00	499.00 N/A 499.00 8,450.00 250.00 9,698.00	NO BID
23.	New World Potable Water Elevated Storage Tank 2.0 MG, 70 feet diam.; 164 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,650.00 250.00 3,898.00	

F281-629	9 (Rev. 5/92)	13-5078			
FOR: TIME & DATE:	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
ITEM NO.	Sea World Potable Water Ground Storage Tank		A L H H		ПСН
24.	2 MG, 85 feet diam.; 50 feet overall height; Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,400.00 150.00 2,255.00	499.00 N/A 499.00 3,650.00 250.00 4,898.00	
25.	Texas Research Park Welded Steel Potable Water Ground Storage Tank 0.25 MG, 54 feet diam.; 15 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 150.00 289.00 1,100.00 150.00 1,889.00	499.00 N/A 499.00 1,250.00 250.00 2,498.00	NO BID
26.	Texas Research Park Prestressed Concrete Potable Water Ground Storage Tank 2.0 MG, 103 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 3,650.00 250.00 4,898.00	NO BID
27.	West Avenue Potable Water Elevated Storage Tank 0.5 MG, 50 feet diam.; 145 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,150.00 250.00 3,398.00	

F281-629	9 (Rev. 5/92)	13-5078	I		
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
28.	Minor Repairs (Item F) Hourly Rate for 40 hours TOTAL Emergency Services (Item E)		250.00 10,000.00 10,000.00	200.00 8,000.00 8,000.00 1,150.00	
29.	4 ea. Mobilation 60 hours., Hourly Rate TOTAL		0.00 350.00 21,000.00 21,000.00	4,600.00 200.00	
1.	TOTAL AMOUNT FOR YEAR 2014 (ITEMS 1-28) 2015 TANK INSPECTION & CLEANING PRICING LIST 34th St. Potable Water Ground Storage Tank 5 MG; 164.5 feet diam.; 44.3 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		99,292.00 250.00 200.00 325.00 3,800.00 200.00 4,775.00	8,400.00	NO BID
2.	Anderson Potable Water Ground Storage Tank No. 1 7.5 MG; 165 feet diam.; 48 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 200.00 325.00 3,800.00 200.00 4,775.00	499.00 N/A 499.00 10,250.00 250.00 11,498.00	
3.	ASR Clearwell No.2 Potable Water Ground Storage Tank 7.5 MG; 227 feet diam.; 47.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 200.00 350.00 4,750.00 250.00 5,800.00	499.00 N/A 499.00 10,250.00	

F281-629	(Rev. 5/92)	13-5078			
PROPOSAL FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		F P A	ВЧН.	L B
	Babcock Potable Water Elevated Storage Tank 2.5 MG; 104 feet diam.; 160 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation		230.00 150.00 325.00 1,500.00 150.00	499.00 N/A 499.00 2,850.00 250.00	
4.	TOTAL		2,355.00	4,098.00	
5.	Broadview Potable Water Ground Storage Tank 4.5 MG; 138 feet diam.; 42.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 8,150.00 250.00 9,398.00	
6.	Callaghan Potable Water Elevated Storage Tank 1.0 MG; 91.3 feet diam; 39 feet bowl height; 112.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,150.00 250.00 3,398.00	NO BID
7.	Devine Reuse Water Elevated Storage Tank 1.2 MG; 84 feet diam.; 43 feet bowl height; 83 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,150.00 4,505.00	499.00 N/A 499.00 2,550.00 250.00 850.00 4,648.00	

F281-629	(Rev. 5/92)	13-5078			
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		ater Services, 6 6126	rices S	ing, Corp. d. 108-0230
PROPOSAL FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY		Am Inc. P.O Ft V	Цу 12 Ч	Lia 7 I Bï
8.	East Houston Reuse Water Ground Storage Tank 1.0 MG; 75 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,150.00 4,505.00	499.00 N/A 499.00 2,350.00 250.00 750.00 4,348.00	
0.	Pearsall Reuse Water Ground Storage Tank		4,505.00	-,5-10:00	
9.	2.5 MG; 120 feet diam.; 33 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		250.00 175.00 325.00 1,600.00 175.00 2,800.00 5,325.00	499.00 N/A 499.00 3,450.00 250.00 1,250.00 5,948.00	NO BID
10	Pinn Rd. Reuse Water Ground Storage Tank 3 MG; 84 feet diam.; 80 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees		230.00 150.00 325.00 1,500.00 150.00 2,150.00	499.00 N/A 499.00 4,150.00 250.00 1,575.00	
10.	TOTAL Solo de Betable Water Cround Sterroge Tenk		4,505.00	6,973.00	
11.	Salado Potable Water Ground Storage Tank 5 MG, 172.0 feet diam.; 30.5 feet overall height; Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 200.00 325.00 2,800.00 150.00 3,725.00	499.00 N/A 499.00 8,400.00 250.00 9,648.00	

SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449	es,		
TABULATION OF BIDS TABULATION OF BIDS PROPOSAL Annual Contract for FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection TIME & (January 1, 2014 through December 31, 2014) DATE: 3:00 p.m., November 12, 2013 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY	American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
South Foster Potable Water Storage Tank 2.0 MG, 100 feet diam.; 40 feet bowl height; 164.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation 12. TOTAL Turtle Creek #2 Potable Water Ground Storage Tank No. 1 0.5 MG, 52 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation	230.00 200.00 325.00 2,800.00 150.00 3,705.00 230.00 150.00 300.00 1,400.00 150.00	499.00 N/A 499.00 5,800.00 250.00 7,048.00 499.00 N/A 499.00 1,950.00 250.00	
13. TOTAL Turtle Creek #2 Potable Water Ground Storage Tank No. 2 0.5 MG, 52 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation 14. Wurzbach Potable Water Ground Storage Tank No. 1 7.5 MG, 181 feet diam.; 40 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation 15.	2,230.00 230.00 150.00 300.00 1,400.00 150.00 2,230.00 250.00 200.00 350.00 4,000.00 150.00 4,950.00	3,198.00 499.00 N/A 499.00 1,950.00 250.00 3,198.00 N/A 499.00 N/A 499.00 10,250.00 250.00 11,498.00	NO BID

F281-629	(Rev. 5/92)	13-5078			
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>16.</u>	Wurzbach Potable Water Ground Storage Tank No. 2 7.5 MG, 181 feet diam.; 40 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 3,800.00 150.00 4,655.00	499.00 N/A 499.00 10,250.00 250.00 11,498.00	
17.	Edgewood (SW 21 st St) Potable Water Ground Storage Tank 1 MG; 75 feet diam.; 34 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 300.00 2,800.00 150.00 3,630.00	499.00 N/A 499.00 2,250.00 250.00 3,498.00	
	General McMullen Potable Water Elevated Storage Tank 0.25 MG; 40 feet diam.; 136 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		230.00 150.00 289.00 1,250.00 150.00	499.00 N/A 499.00 1,450.00 250.00	NO BID
<u>18.</u> 19.	TOTAL Golden Potable Water Ground Storage Tank 12.5 MG; 226 feet diam.; 50 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		2,069.00 350.00 275.00 400.00 3,800.00 175.00 5,000.00	2,698.00 499.00 N/A 499.00 14,500.00 250.00 15,748.00	
20.	Hutchins Potable Water Elevated Storage Tank 0.5 MG; 50 feet diam.; 159 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,400.00 150.00 2,255.00	499.00 N/A 499.00 1,650.00 250.00 2,898.00	

F281-629	(Rev. 5/92)	13-5078		1	
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
21.	King Potable Water Ground Storage Tank 0.5 MG; 52 feet diam.; 34 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 289.00 1,100.00 150.00 1,919.00	499.00 N/A 499.00 1,950.00 250.00 3,198.00	
22.	La Rosa Potable Water Ground Storage Tank 3 MG; 122 feet diam.; 34 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,600.00 1,500.00 3,805.00	499.00 N/A 499.00 4,250.00 250.00 5,498.00	
23	Somerset Potable Water Ground Storage Tank 0.3 MG; 40 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOT AL		230.00 150.00 289.00 1,100.00 150.00	499.00 N/A 499.00 1,650.00 250.00	NO BID
<u>23.</u> 24.	TOTAL Vestal Potable Water Elevated Storage Tank 1.5 MG; 91 feet diam.; 162 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		1,919.00 230.00 150.00 325.00 1,500.00 150.00 2,355.00	2,898.00 499.00 N/A 499.00 2,250.00 250.00 3,498.00	
25.	West Avenue Potable Water Elevated Storage Tank 0.5 MG, 50 feet diam.; 145 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 1,650.00 250.00 2,898.00	

F281-629	(Rev. 5/92)	13-5078			
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		rater Services, 6 5126	vices S 3	eering, Corp. t Rd. 59108-0230
PROPOSAL FOR: TIME & DATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY Wild Turkey Potable Water Ground Storage Tank 0.5 MG, 55 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation		マ 丘 広 230.00 150.00 325.00 1,500.00 150.00	499.00 N/A 499.00	1 Li 13
<u>26.</u> 27.	TOTAL Minor Repairs (Item F) Hourly Rate for 40 hours TOTAL		2,355.00 250.00 10,000.00 10,000.00	· · ·	
28.	Emergency Services (Item E) 4 ea. Mobilation 60 hours., Hourly Rate		0.00 350.00 21,000.00	1,150.00 4,600.00 200.00	
	TOTAL		21,000.00	16,600.00	
	TOTAL AMOUNT FOR YEAR 2015 (ITEMS 1 – 28) 2016 TANK INSPECTION & CLEANING PRICING LIST Artesia Potable Water Ground Storage Tank 5 MG; 164.5 feet diam.; 42.3 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning cost per additional 1" of sedimentation Torot AL		121,412.00 230.00 150.00 325.00 1,500.00 150.00 2355.00	499.00 N/A 499.00 8,400.00 250.00	NO BID
<u>1.</u> 2.	TOTAL Brooks Reuse Water Ground Storage Tank 0.5 MG; 54 feet diam.; 27 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		2,355.00 230.00 150.00 289.00 1,400.00 150.00 2,150.00 4,369.00	N/A 499.00 2,250.00 250.00	

F281-6	29 (Rev. 5/92)	13-5078		1	
PROPOSA FOR: TIME & DATE: ITEM NC	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS AL Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
3.	Coliseum Reuse Water Elevated Storage Tank 0.5 MG; 75 feet diam.; 43 feet bowl height; 140 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,150.00 4,505.00	499.00 N/A 499.00 2,150.00 250.00 850.00 4,248.00	
4.	Concept Therapy Potable Water Concrete Standpipe No. 1 0.03 MG; 10 feet diam.; 36 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 300.00 1,400.00 150.00 2,150.00	499.00 N/A 499.00 850.00 250.00 2,098.00	
5.	Concept Therapy Potable Water Concrete Standpipe No. 2 0.03 MG; 10 feet diam.; 36 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 300.00 1,400.00 100.00 2,100.00	499.00 N/A 499.00 850.00 250.00 2,098.00	NO BID
6.	Concept Therapy Potable Water Concrete Standpipe No. 3 0.03 MG; 10 feet diam.; 36 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 300.00 1,400.00 100.00 2,100.00	499.00 N/A 499.00 850.00 250.00 2,098.00	
7.	Concept Therapy Potable Water Hydro-pneumatic Tank 0.01 MG; 6.0 feet diam.; 24 inches Water/Level Tank; 6.0 feet length Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Cleaning Cost In-service (not-drained) TOTAL		200.00 100.00 300.00 600.00	299.00 125.00 1,150.00 1,574.00	

F281-62	29 (Rev. 5/92)	13-5078		1	1
PROPOSA FOR: TIME & DATE: ITEM NO	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS AL Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>8.</u>	Dos-Rios Reuse Water Hydro-Pneumatic Tank 2.0 MG; 10 feet diam.; 6.5 feet Water Level Tank; 40 feet length Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Drained Cleaning Cost Out Of Service TOTAL		200.00 50.00 300.00 550.00	299.00 125.00 2,150.00 2,574.00	
9.	Fredericksburg Reuse Water Elevated Storage Tank 1.0 MG; 74 feet diam.; 38 feet bowl height; 135 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,150.00 4,505.00	499.00 N/A 499.00 2,450.00 250.00 750.00 4,448.00	
10.	General McMullen Potable Water Elevated Storage Tank 2 MG; 95 feet diam.; 45 feet bowl height; 135 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,650.00 250.00 3,898.00	NO BID
11.	Helotes / Adobe Ranch Potable Water Ground Storage Tank 5 MG; 150 feet diam.; 41.8 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 200.00 325.00 2,100.00 150.00 3,005.00	499.00 N/A 499.00 8,400.00 250.00 9,648.00	
12.	Helotes Park #3 Potable Water Standpipe 0.27 MG; 21.5 feet diam.; 100 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 100.00 350.00 1,500.00 100.00 2,280.00	499.00 N/A 499.00 2,150.00 250.00 3,398.00	

F281-629	(Rev. 5/92)	13-5078		1	
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>13.</u>	Hills Potable Water Ground Storage Tank 3 MG; 90 feet diam.; 64 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 4,250.00 250.00 5,498.00	
14.	Judson Potable Water Elevated Storage Tank 0.5 MG; 40 feet diam.; 139.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,400.00 150.00 2,255.00	499.00 N/A 499.00 1,650.00 250.00 2,898.00	
15.	Marshall Potable Water Ground Storage Tank 0.55 MG; 55 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 300.00 1,400.00 150.00 2,230.00	499.00 N/A 499.00 2,150.00 250.00 3,398.00	NO BID
16.	Naco Potable Water Ground Storage Tank 7.5 MG; 165 feet diam.; 52.2 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 350.00 1,650.00 150.00 2,530.00	499.00 N/A 499.00 10,250.00 250.00 11,498.00	
17.	Randolph Potable Water Ground Storage Tank 5 MG; 165 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 350.00 1,650.00 150.00 2,530.00	499.00 N/A 499.00 8,400.00 250.00 9,648.00	

F281-62	9 (Rev. 5/92) 13-	3-5078			
PROPOSA FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
18.	Seale Potable Water Ground Storage Tank No. 2 3 MG; 90 feet diam.; 64.5 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 323.00 1,500.00 150.00 2,353.00	499.00 N/A 499.00 4,250.00 250.00 5,498.00	
10	Stotzer Reuse Water Ground Storage Tank 2.2 MG, 84.0 feet diam.; 51.0 feet overall height; Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained). Cleaning Cost In-service (not-drained). Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		230.00 150.00 300.00 1,500.00 150.00 2,150.00	499.00 N/A 499.00 3,450.00 250.00 1,250.00	
<u>19.</u> 20.	IOTAL Winwood Potable Water Ground Storage Tank 2 MG; 84 feet diam.; 48 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		4,480.00 230.00 150.00 300.00 1,500.00 150.00 2,330.00	5,948.00 499.00 N/A 499.00 3,250.00 250.00 4,498.00	NO BID
21.	Winwood Potable Water Hydro-Pneumatic Storage Tank3MG; 10 feet diam.; 7 feet overall height; 36 feet lengthInspection Cost DrainedDrained Cleaning cost per additional 1" of sedimentationDrained Cleaning Cost Out Of ServiceTOTAL		200.00 100.00 300.00 600.00	299.00 125.00 2,050.00 2,474.00	
22.	Cagnon Potable Water Ground Storage Tank 1.0 MG; 74.0 feet diam.; 34.0 feet Water Level Tank Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 1,950.00 250.00 3,198.00	

	(Rev. 5/92)	13-5078	I	I I	
PROPOSAL FOR:	P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
IME & ATE:	(January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Inc. P.O. Box 1 Ft Worth, '	as Ta 07 H ər, T'	uid E ast A ings,
	DESCRIPTION AND APPROXIMATE QUANTITY		Ame Inc. P.O. Ft W	Texas 12907 Tyler,	7 Ei Bill
	Cagnon Potable Water Elevated Storage Tank	Ī	, , , , , , , , , , , , , , , , , , , ,		
	1.0 MG; 64 feet diam.; 168 feet overall height				
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		150.00	499.00 N/A	
			325.00	499.00	
	Inspection Cost In-service (not-drained)				
	Cleaning Cost In-service (not-drained)		1,500.00	1,950.00	
	Underwater Cleaning cost per additional 1" of sedimentation		150.00	250.00	
			2,355.00	3,198.00	
	CR3820 Potable Water Ground Storage Tank				
	0.25 MG; 39 feet diam.; 32 feet to overflow		220.00	100.00	
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		150.00	N/A	
	Inspection Cost In-service (not-drained)		289.00	499.00	
	Cleaning Cost In-service (not-drained)		1,100.00	1,750.00	
	Underwater Cleaning cost per additional 1" of sedimentation		150.00	250.00	
	TOTAL		1,919.00	2,998.00	
	Far West Potable Water Ground Storage Tank				
	0.5 MG; 61 feet diam.; 24 feet to overflow				
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		150.00	N/A	
	Inspection Cost In-service (not-drained)		300.00	499.00	NO BIE
	Cleaning Cost In-service (not-drained)		1,500.00	2,050.00	NO DIL
	Underwater Cleaning cost per additional 1" of sedimentation		150.00	250.00	
5.	TOTAL		2,330.00	3,298.00	
	Stevens Ranch Potable Water Elevated Storage Tank				
	2.5 MG; 103.0 feet diam.; 205.0 feet overall height				
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		150.00	N/A	
	Inspection Cost In-service (not-drained)		325.00	499.00	
	Cleaning Cost In-service (not-drained)		1,650.00	2,850.00	
	Underwater Cleaning cost per additional 1" of sedimentation		150.00		
	TOTAL		2,505.00	4,098.00	
	Minor Repairs (Item F)		250.00	200.00	
	Hourly Rate for 40 hours		10,000.00	8,000.00	
	TOTAL		10,000.00	8,000.00	
	Emergency Services (Item E)			1,150.00	
	4 ea. Mobilation		350.00	4,600.00	
	60 hours., Hourly Rate		21,000.00		
	ov nouis, moully Rate		21,000.00	12,000.00	
28.	TOTAL		21 000 00		
<u>o</u> .	TOTAL		21,000.00	16,600.00	
<u> </u>					

281-629	(Rev. 5/92) 13	3-5078	1		
	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	rvices 5 S 33	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
ROPOSAL DR: IME & ATE:	Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013		American Undera Inc. P.O. Box 126216 Ft Worth, TX 761	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	id Enginee st Airport] ngs, MT 59
			Ame Inc. P.O. Ft W	ex: 29(illi Billi
'EM NO.	DESCRIPTION AND APPROXIMATE QUANTITY 2017 TANK INSPECTION & CLEANING PRICING LIST		≺дцц	L L L	ЦИЦ
	Devine Reuse Water Elevated Storage Tank				
	1.2 MG; 84 feet diam.; 83 feet overall height		220.00	400.00	
	Inspection Cost Drained		230.00	499.00 N/A	
	Drained Cleaning cost per additional 1" of sedimentation		150.00		
	Inspection Cost In-service (not-drained)		325.00 1,500.00	499.00	
	Cleaning Cost In-service (not-drained)		1,500.00	2,450.00 250.00	
	Underwater Cleaning cost per additional 1" of sedimentation				
	Sedimentation Transport fees TOTAL		2,400.00	1,250.00	
	Dwyer Potable Water Elevated Storage Tank		4,755.00	4,948.00	
	1 MG; 75 feet diam.; 173 feet overall height				
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		150.00	N/A	
	Inspection Cost In-service (not-drained)		325.00	499.00	
	Cleaning Cost In-service (not-drained)		1,500.00	2,150.00	
	Underwater Cleaning cost per additional 1" of sedimentation		150.00	250.00	
	TOTAL		2,355.00	3,398.00	
	East Houston Reuse Water Ground Storage Tank				
	1 MG; 75 feet diam.; 32 feet overall height		230.00	499.00	
	Inspection Cost Drained		150.00	499.00 N/A	NO BID
	Drained Cleaning cost per additional 1" of sedimentation				NO DIL
	Inspection Cost In-Service (not-drained)		325.00 1,500.00	499.00 2,350.00	
	Cleaning Cost In-Service (not-drained)		1,500.00	2,350.00	
	Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees		2,150.00	230.00 750.00	
			4,505.00	4,348.00	
	TOTAL Helotes Park #2		-+,505.00	7,340.00	
	0.1 MG; 20 feet diam.; 108 feet overall height				
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		100.00	499.00 N/A	
	Inspection Cost In-service (not-drained)		325.00	499.00	
	Cleaning Cost In-service (not-drained)		1,400.00	1,650.00	
	Underwater Cleaning cost per additional 1" of sedimentation		150.00	250.00	
	TOTAL		2,205.00	2,898.00	
	Lockhill Potable Water Elevated Storage Tank			_,0>0.00	
	1.5 MG; 91.3 feet diam.; 195 feet overall height				
	Inspection Cost Drained		230.00	499.00	
	Drained Cleaning cost per additional 1" of sedimentation		150.00	N/A	
	Inspection Cost In-service (not-drained)		325.00	499.00	
	Cleaning Cost In-service (not-drained)		1,500.00	2,250.00	
	Underwater Cleaning cost per additional 1" of sedimentation		150.00	250.00	
	TOTAL 19		2,355.00	3,498.00	

F281-629	(Rev. 5/92)	13-5078			
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
6.	Maltsberger Potable Water Ground Storage Tank 7.5 MG; 165 feet diam.; 48 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 200.00 350.00 3,800.00 200.00 4,800.00	499.00 N/A 499.00 10,250.00 250.00 11,498.00	
7.	Menger Potable Water Elevated Storage Tank 1.5 MG; 88 feet diam.; 105 feet to overflow Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,500.00 150.00 2,355.00	499.00 N/A 499.00 2,250.00 250.00 3,498.00	
	Pinn Rd. Reuse Water Ground Storage Tank 3 MG; 84 feet diam.; 80 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees		230.00 150.00 325.00 1,650.00 150.00 2,500.00	499.00 N/A 499.00 6,250.00 250.00 1,450.00	NO BID
<u>8.</u> 9.	TOTAL Ranch Town No. 2 Potable Water Ground Storage Tank 1 MG; 80 feet diam.; 27 feet height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		5,005.00 230.00 150.00 325.00 1,500.00 150.00 2,355.00	8,948.00 499.00 N/A 499.00 1,950.00 250.00 3,198.00	
10.	Redland Potable Water Elevated Storage Tank 2.0 MG; 105 feet diam.; 91 feet to overflow Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,600.00 150.00 2,455.00	499.00 N/A 499.00 2,650.00 250.00 3,898.00	

F281-629	(Rev. 5/92)	13-5078			
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
<u>11.</u>	Shields Potable Water Reservoir Storage Tank 5.0 MG; 116.5.0 feet diam.; 73.0 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 200.00 325.00 1,650.00 150.00 2,555.00	499.00 N/A 499.00 8,400.00 250.00 9,648.00	
12.	Woods of Fair Oaks Potable Water Ground Storage Tank No. 1 0.48 MG; 24 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 289.00 1,250.00 150.00 2,069.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	
13.	Woods of Fair Oaks Potable Water Ground Storage Tank No. 2 0.46 MG; 22 feet diam.; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 289.00 1,250.00 150.00 2,069.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	NO BID
14.	Village Green Potable Water Ground Storage Tank 0.155 MG; 28 feet diam; 32 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 289.00 1,250.00 150.00 2,069.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	
15.	Anaqua Springs Potable Water Ground Storage Tank 1 0.06 MG; 26 feet diam.; 16 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 289.00 1,100.00 100.00 1,789.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	

F281-629	9 (Rev. 5/92)	13-5078			
PROPOSAI FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
16.	Anaqua Springs Potable Water Ground Storage Tank 2 0.06 MG; 26 feet diam.; 16 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 289.00 1,100.00 100.00 1,789.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	
<u>17.</u>	Anaqua Springs Potable Water Ground Storage Tank 3 0.06 MG; 26 feet diam.; 16 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 289.00 1,100.00 100.00 1,789.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	
18.	Anaqua Springs Potable Water Ground Storage Tank 4 0.06 MG; 26 feet diam.; 16 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 289.00 1,100.00 100.00 1,789.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	NO BID
19.	Bear Springs Potable Water Ground Storage Tank 0.28 MG; 32 feet diam.; 48 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		200.00 100.00 289.00 1,100.00 100.00 1,789.00	499.00 N/A 499.00 1,450.00 250.00 2,698.00	
20.	Edgewood (SW 21 st) Potable Water Ground Storage Tank 1.0 MG; 75 feet diam.; 34 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		230.00 150.00 325.00 1,650.00 150.00 2,505.00	499.00 N/A 499.00 1,950.00 250.00 3,198.00	

F281-629	(Rev. 5/92)	13-5078	1		
PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Annual Contract for Potable and Reuse Water Storage Tank Cleaning and Inspection (January 1, 2014 through December 31, 2014) 3:00 p.m., November 12, 2013 DESCRIPTION AND APPROXIMATE QUANTITY		American Underater Services, Inc. P.O. Box 126216 Ft Worth, TX 76126	Texas Tank Services 12907 Hwy 155 S Tyler, TX 75703	Liquid Engineering, Corp. 7 East Airport Rd. Billings, MT 59108-0230
112.4110.	Lemonwood Potable Water Ground Storage Tank				
<u>21.</u> <u>22.</u> 23.	 1.0 MG; 75 feet diam.; 34 feet overall height Inspection Cost Drained Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning Cost In-service (not-drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL Minor Repairs (Item F) Hourly Rate for 40 hours TOTAL Emergency Services (Item E) 4 ea. Mobilation 60 hours., Hourly Rate TOTAL		10,000.00 10,000.00 0.00	N/A 499.00 1,950.00 250.00 3,198.00 200.00 8,000.00 8,000.00 1,150.00 4,600.00 200.00 12,000.00	NO BID
	TOTAL AMOUNT FOR YEAR 2015 (ITEMS 1 – 28)		86,862.00	112,358.00	
	TOTAL CONTRACT AMOUNT FOR YEARS 2014-2017		* 402,567.00 5%	585,621.00 1%	
	Terms *LOW BIDDER		7 days	20 days	

BID INVITATIONS WERE MAILED TO AND/OR PICKED UP BY:

American Underwater Services, Inc. Liquid Engineering Corp. Texas Tank Services