

**SAN ANTONIO WATER SYSTEM**  
**P. O. BOX 2449**  
**SAN ANTONIO, TEXAS 78298-2449**  
**TABULATION OF BIDS**

PROPOSAL Removal of Asbestos Containing Material (ACM) of Boiler at Heating and Cooling Plant and Third Party Air Monitoring  
 FOR:  
 TIME &  
 DATE: 3:00 p.m., February 24, 2016

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

			1 Priority Environmental Services 5504 Bandera Road, Ste. 616 San Antonio, TX 78238	Alamo1 12400 San Pedro Ave., Suite 200 San Antonio, TX 78216	AEHS, Inc. 4402 Center Gate San Antonio, TX 78217	
	Approx. Qty: 130 square feet Asbestos Containing Building Material: Partially Dismantled Boiler Asbestos Content: 3% Chrysotile, Location: Main Bldg.	UNIT PRICE TOTAL	84.23 10,949.90	9,251.00 1,202,630.00	<b>BID NOT TABULATED INCOMPLETE BID</b>	
	Approx. Qty: 130 square feet Asbestos Containing Building Material: Intact Boiler Asbestos Content: 3% Chrysotile, Location: Main Bldg.	UNIT PRICE TOTAL	84.23 10,949.90	13,878.00 1,804,140.00		
	Approx. Qty: Unknown Lump Sum Asbestos Containing Building Material: Assumed Asbestos Content: Assumed, Location: Covered Debris Pile	TOTAL	8,300.00	9,270.00		
	2 ea. Disposal Steam Boilers 1 & 2 at the Central Heating & Cooling Plant		16,850.00 33,700.00	25,235.00 50,470.00		
	<b>TOTAL</b>		<b>63,899.80</b>	<b>3,066,510.00</b>		
	Terms		Net 30 days	1% 10 days	Net 30 days	
	Delivery					

**\*LOW BID**

**\*\*ERROR ON PRICING SHEET, VENDOR PUT EXTENDED PRICE AS UNIT PRICE**

BID INVITATIONS E-MAILED TO AND/OR PICKED UP BY:

1 Priority Environmental Services  
 AEHS, Inc.  
 Alamo1  
 Ashley Salvage  
 Bay Metal  
 CMC  
 Frontline1  
 Gruene Environmental  
 Hunter Demolition

Longhorn Recycling  
 M Contracting  
 Monterrey Iron  
 Ramon Demolition  
 Robles1  
 SW TX Environmental  
 SWS Environmental  
 Whittaker Lane

Demandstar  
 SAWS Website