F281-629 (Rev. 5/92) 12-1258

PROPOSAL FOR: TIME & DATE: ITEM NO.	SAN ANTONIO WATER SYSTEM P. O. BOX 2449 SAN ANTONIO, TEXAS 78298-2449 TABULATION OF BIDS Purchase of Fire Cleanup and Restoration Services Basin Pump Station 3:00 p.m., May 30, 2012 DESCRIPTION AND APPROXIMATE QUANTITY		Blackmon Mooring of TX 4808 Perrin Creek San Antonio, TX 78217	FST Construction 15103 SW Loop 410 San Antonio, TX 78221	
1.	1 LS Cleaning of Ceiling Fixutres - Cleana nd replace plastic lenses of existing ceiling mounted fluorescent light fixtures and air diffusers	UNIT PRICE TOTAL	1,205.03		
2.	1 LS Air Scrubbing - Air Scrubbing of Ground Floor and Basement, using High Efficiency particulate arrestor to remove airborn particles 0.3 microns or larger	UNIT PRICE TOTAL	8,106.78	BID NOT TABULATED NON RESPONSIVE	
3.	1 LS Smoke Odor Remover - Smoke and Odor Removal of Ground Floor and Basement, using Ozone generation to remove airborn smoke odor molecules	UNIT PRICE TOTAL	6,328.02		
4.	1 LS Groundfloor Surfaces - Cleaning by wipe-down, vacuuming/mop-down of all wall, floor, structural and equipment vertical and horizontal surfaces	UNIT PRICE TOTAL	8,420.98		
5.	1 LS Basement Surfaces - Cleaning by wipe-down, vacuuming/mop-down of all wall, ceiling, floor, structural, and equipment vertical and horizontal surfaces	UNIT PRICE TOTAL	6,652.53		
	TOTAL	TOTAL	* 30,713.34		
	Terms		3% 15 days		
	Delivery Days				

*LOW BIDDER

BID INVITATIONS MAILED TO AND/OR PICKED UP BY:

Belfor

Blackmon Mooring of TX

BMF Cat

Cotton (Global Disaster Solutions)

Emergency Remediation Medics

FST Construction

Gerloff Co., Inc.

Interstate Consulting Services

Service Master Restoration

Steamatic

SAWS Website