

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL FOR: **Sanitary Sewer Pole Camera Inspection "Year 1"**
 TIME & DATE: **3:00 p.m., September 19, 2013**
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

			Burgess & Niple, Inc. 4029 S. Capital of TX Hwy, Ste. 220 Austin, TX 78704	Pipeline Video Inspection, LLC 1616 S. 31st Ave. Phoenix, AZ 85009	Wachs Valve and Hydrant Services, LLC 801 Asbury Drive Buffalo Grove, IL 60089	RJN Group, Inc. 14546 Brook Hollow Blvd., Suite 218 San Antonio, TX 78232	Hoffman Southwest Corp. dba Professional Pipe Services 4940 W. Watkins st. Phoenix, AZ 85043
1	1,516 ea. Pole Camera Inspection of Pipelines and Manholes in accordance with the specifications	UNIT PRICE 88.00 TOTAL 133,408.00	88.00 133,408.00	88.00 133,408.00	145.00 219,820.00	175.00 265,300.00	BID NOT TABULATED CONDITIONAL BID
2	40 hours Provide Police Officer Services when required by the Governing Right-of-Way Agency	UNIT PRICE 40.00 TOTAL 1,600.00	40.00 1,600.00	75.00 3,000.00	38.00 1,520.00	50.00 2,000.00	
	TOTAL ESTIMATED PRICE	TOTAL 135,008.00	135,008.00	136,408.00	221,340.00	267,300.00	
	Terms		2% 10 days	Net 30 days	Net 30 days	Net 30 days	
	Delivery Days						

***LOW BIDDER**

Burgess & Niple
 InfraMetrix
 Pipeline Analysis
 Pipeline Video Inspection

Demandstar
 SAWS