

## September 24, 2019

U.S. Environmental Protection Agency, Region VI Chief, Water Enforcement Branch (6EN-W) Compliance Assurance and Enforcement Division 1445 Ross Avenue Dallas, TX 75202-2733

Via U.S. Certified Mail RRR#7017 0530 0001 0086 1988

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (6EN-W) Environmental Protection Specialist Enforcement Branch 1445 Ross Avenue Dallas, TX 75202-2733 Via U.S. Certified Mail RRR# 7017 0530 0001 0086 1988

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

#### Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. A copy of a five-day report submitted to TCEQ on September 24, 2019 is attached and is provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Vice President

Production & Treatment

Enc. as stated



# September 24, 2019

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611 Washington, D.C. 20044-7611

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 1995

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

### Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. A copy of a five-day report submitted to TCEQ on September 24, 2019 is attached and is provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Vice President

Production & Treatment

Enc. as stated

# Water Quality Noncompliance Notification

X Unautho	orized Discl	harge of Wa	astewater	Rep	Reportable Effluent Violation			
General Inform	nation							
ntity Name: San Antonio Water System			Telephone: 210-233			33-3274		
X Permitte				Subscribe	r			
TCEQ Region:	13	County:	Bexar	Permit Nur	nber	10137-008 <b>-</b> Sala	do Creek	
Noncomplianc	e Summar	/						
	discharge):_	The addres	s of the sp	ill was at 480°	Goldfield (F	mated volume i FERG 193A8) A		
SR#: 2969961	; INSPT#:	590138; W	O#: ; Sewe	er Lift Station L	S023			
Cause of Nonc	compliance	: Other -	Mechanica	al - Lift Station	# 023 Lost I	ower	1	
Duration:	Start	OS (Date	9/20/2019	4:46 (Time)	End	09/20/20 (Date)	19 5:30 (Time)	
	Or exped	cted to be C	orrected					
					(Da	ale)		
Potential Dang	ers to Hum	an Health	and Safety	or the Environ	nment: No S	Significant Dang	ers	
Actions Taken	1							
Monitoring Da	ta: Data sh	ould be atta	ched or su	bmitted to TC	EQ when av	ailable.		
	es	Xno Field Meas			surements			
-	ye	25	X no	Laborato	ory Samples			
	y	es	X no	Fish Kilt,	If yes, estimate	ed number killed _		
Actions Taken	to Mitigate	Adverse E	ffects: Spi	Il Contained,	Monitored A	Area, Clean Up	s On Going	
Actions Taken	to Correct	the Probler	n and Prev	vent Recurren	ce: Cps Re	estored Power	o Ls023	
Verification In	formation							
Information Reported By			Eric Viera CON Operator III (Name) (Title)					
Date Reported	d	9/20/2019		Signature:	Fell			
TCEQ 0501 (Nov	ember 5, 200	2) If the nonce	ompliance is	an unauthorized of	discharge from	a wastewater collection system is the	ction system, use	

TCEQ Region 13 Fax: 545-4329

TCEQ Region 13 Phone: 490-3096