

January 10, 2020

U.S. Environmental Protection Agency, Region VI Chief, Water Enforcement Branch (6EN-W) Compliance Assurance and Enforcement Division 1445 Ross Avenue Dallas, TX 75202-2733 Via U.S. Certified Mail RRR# 7017 0530 0001 0086 5290

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (6EN-W) Environmental Protection Specialist Enforcement Branch 1445 Ross Avenue Dallas, TX 75202-2733

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 5290

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

#### Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on January 10, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely,

Vice President

Production & Treatment

Enc. as stated



#### January 10, 2020

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 5283

Washington, D.C. 20044-7611

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San

Antonio Division

### Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on January 10, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely,

Jeffrey J. Haby, P.E. Vice President

Production & Treatment

Enc. as stated

## **Water Quality Noncompliance Notification**

	Reportable Effluent Violation Othr
General Information	
Entity Name: San Antonio Water System	Telephone: 210-233-3274
X Permitte	Subscriber
TCEQ Region: 13 County: Bexar Per	mit Number 10137-003-Leon Creek
Noncompliance Summary	
Description of Noncompliance (include location, discharge discharge): The address of the spill was at 12290 Applewhi River/Creek Comanche Creek Spilled From Manhole #372	te Rd, , Approximately 3,340 Gallons Spilled Into
Case #: 2300 / SR#: 3110795 / INSP#: 609577 / WO#: 178	0640 / SRC: Sewer Main 37248 37102
Cause of Noncompliance: Structural	
Duration: Sewer Manhole 37226 / Start 01/07/2020 10:5	8 / End 01/07/2020 13:45 / Hrs 2.78 / Gals 3340
Potential Dangers to Human Health and Safety or the	Environment: No Significant Dangers
Actions Taken	
	d to TCEQ when available.
	d to TCEQ when available. Field Measurements
Monitoring Data: Data should be attached or submitte	
Monitoring Data: Data should be attached or submitte	Field Measurements
Monitoring Data: Data should be attached or submitte  yesX no  yesX no  yesX no	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed
Monitoring Data: Data should be attached or submitte	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed
Monitoring Data: Data should be attached or submitte	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed
Monitoring Data: Data should be attached or submitte	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  ined, Cleanup Is Ongoing
Monitoring Data: Data should be attached or submitte	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  inned, Cleanup Is Ongoing  ecurrence: 21 Inch Sewer Main, D&C Crews
Monitoring Data: Data should be attached or submitte  yesXno  yesXno  yesXno  yesXno  Actions Taken to Mitigate Adverse Effects: Spill Contact  Actions Taken to Correct the Problem and Prevent Re Pumped And Hauled To Stop Spill And Setup Bypass Created For Repairs On Mh#37248	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  inned, Cleanup Is Ongoing  ecurrence: 21 Inch Sewer Main, D&C Crews
Monitoring Data: Data should be attached or submitte	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  inned, Cleanup Is Ongoing  ecurrence: 21 Inch Sewer Main, D&C Crews
Monitoring Data: Data should be attached or submitte  yesX	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  lined, Cleanup Is Ongoing  currence: 21 Inch Sewer Main, D&C Crews Operations Wo# 1780640 & Wo# 1780642 Were
Monitoring Data: Data should be attached or submitte  yesXno yesXno yesXno Actions Taken to Mitigate Adverse Effects: Spill Contact  Actions Taken to Correct the Problem and Prevent RePumped And Hauled To Stop Spill And Setup Bypass Created For Repairs On Mh#37248  Verification Information	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  lined, Cleanup Is Ongoing  currence: 21 Inch Sewer Main, D&C Crews  Operations Wo# 1780640 & Wo# 1780642 Were
Monitoring Data: Data should be attached or submitte  yesXno yesXno yesXno yesXno Actions Taken to Mitigate Adverse Effects: Spill Conte Actions Taken to Correct the Problem and Prevent Re Pumped And Hauled To Stop Spill And Setup Bypass Created For Repairs On Mh#37248  Verification Information  Information Reported By Roy A Trevino	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  Lined, Cleanup Is Ongoing  Ecurrence: 21 Inch Sewer Main, D&C Crews Operations Wo# 1780640 & Wo# 1780642 Were  / LC/TV OPERATOR III (Title) //9/25
Monitoring Data: Data should be attached or submitte	Field Measurements  Laboratory Samples  Fish Kill, If yes, estimated number killed  inned, Cleanup Is Ongoing  courrence: 21 Inch Sewer Main, D&C Crews Operations Wo# 1780640 & Wo# 1780642 Were  / LC/TV OPERATOR III (Title) // A/Zo  JANATTE Auron Dr. 005 Jup.

# **Water Quality Noncompliance Notification**

_X_ Un	X Unauthorized Discharge of Wastewater					Reportable Effluent Violation Oti			
General I	nforma	ation							
Entity Nar	ne:	San Antoi	nio Water S	ystem		Telephone	:	210-233-32	.74
X Per	mitte			_	Subscribe	er			
TCEQ Re	gion:_	13	County:	Bexar	Permit Nu	mber	10137-00	8-Salado C	reek
Noncomp	liance	Summary	1						
discharge) Approxima Tpc Pkwy Case #: 22	tely 6,3 Main 60 / SI	ddress of t 350 Gallons (~150 Gall R#: 310778	he spill was a s Spilled Into ons Reached to / INSP#: 60	at 2812 Tpc Drainage C d East Elm ( 09347 / SR(	narge route, an Pkwy, Over Thannel Spill Vork, The Rest C: Sewer Main Manhole # 59	he Edwards Vas Contain Was Contain 59168 5916	Aquifer Rec led To Reter ned In Reter	harge Zone,	hat'S Btwn
Duration:	Sewe	r Manhole	59602 / Star	t 01/05/202	0 14:31 / Enc	I 01/05/2020	) 18:45 / Hr	s 4.23 / Gals	6350
		rs to Hum	an Health a	nd Safety (	or the Environ	nment: <u>No</u>	Significant	Dangers	
Actions T	акеп						Marine		
Monitoring	g Data	: Data sho	ould be attac	ched or sub	mitted to TC		available.		
		ує	·	Xno		easurements			
		ye		Xno		ory Samples			
		ye	7	<u>X</u>		, If yes, estima			
Actions T	aken t	o Mitigate	Adverse Ef	fects: Spill	Contained, C	lean Up Is	Ongoing /	Returned	To System
Actions T	aken t	o Correct	the Problem	and Preve	ent Recurren	ce: 8 Inch	Sewer Mai	n, Unstoppe	ed Main
Verification	n Info	rmation							
Information	n Rep	orted By	lsı	ael A Elizo (Name)	ndo Jr	1	9	FOREPERSO (Title)	/ /
Date Rep	orted .		1/5/2020	8	Signature: (	all	(DA	V.	1/7/20
TCEQ 0501	(Nover	nber 5, 2002	!) If the nonco	mpliance is a	n unauthorized of	discharge from to which the c	n a wastewate collection syst	er collection sy em is tied.	slem, use
TCEQ Re	gion 1	3 Phone:	490-3096		1 27				x: 545-4329