

August 11, 2020

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (R6-ECDWA) Water Enforcement Branch U.S. EPA Region 6 1201 Elm Street, Suite 500 Dallas, TX 75270-2102 Via U.S. Certified Mail RRR# 7017 0530 0001 0086 6167

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on August 11, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely

Jeffrey J. Haby, P.E

Vice President

Production & Treatment

Enc. as stated



August 11, 2020

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611 Washington, D.C. 20044-7611

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 6174

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on August 11, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Jeffrey J. Haby, P.E

Vice President

Production & Treatment

Enc. as stated

Water Quality Noncompliance Notification

X Unauthorized Discharge of Wastewater	Reportable Effluent Violation Othr					
General Information						
Entity Name: San Antonio Water System	Telephone: 210-233-3274					
X Permitte	Subscriber					
CEQ Region: 13 County: Bexar	Permit Number 10137-003-Leon Creek					
Noncompliance Summary						
	charge route, and estimated volume if an unauthorized mney , Approximately 9,240 Gallons Spilled Into River/Creek					
Case #: 4500 / SR#: 3383390 / SRC: Sewer Main 4	1713 41714					
Cause of Noncompliance: Vandalism						
The state of the s						
Ouration: Sewer Manhole 41713 / Start 08/06/202	20 09:30 / End 08/06/2020 14:38 / Hrs 5.13 / Gals 9240					
Potential Dangers to Human Health and Safety	or the Environment: No Significant Dangers					
	or the Environment. He digimioant Bangare					
Actions Taken						
Monitoring Data: Data should be attached or su	ubmitted to TCEQ when available.					
X	o Field Measurements					
yesXnc						
yesXnc	Fish Kill, If yes, estimated number killed					
Actions Taken to Mitigate Adverse Effects: <u>Spil</u>	Il Contained, Area Cleaned and Disinfected					
Actions Taken to Correct the Problem and Pro-	vent Recurrence: 18 Inch Sewer Main, Unstopped Main					
actions Taken to correct the Problem and Fred	vent (vecurrence: 10 mcn Sewer Main, Onstopped Main					
Verification Information						
Information Reported By Ricardo J S (Name)	Sanchez / LC/TV OPERATOR II					
	Indiality West Hitter					
	Signature: MENTER INTERPRETATION OF THE STATE OF THE STAT					
	an unauthorized distinarge from a wastewater collection system, use / e treatment plant to which the collection system is tied.					

TCEQ Region 13 Fax: 545-4329

TCEQ Region 13 Phone: 490-3096

Water Quality Noncompliance Notification

X Unauthorized Discharge of Wastewater				Reportable Effluent Violation Othr			
General Inform	mation						
Entity Name:	San Antor	io Water Sy	stem	Telep	ohone:	210-233-3	274
X Permitte			10000	Subscriber			
CEQ Region	13	County:	Bexar	Permit Number	10137-	033-Steven M.	Clouse
loncompliand	ce Summary						
				narge route, and est r W, Approximately			
ase #: 4520 /	SR#: 338579	3 / INSP#: 64	41261 / SRC	Sewer Main 2015	8 20483		
Cause of Non	compliance:	Grease					ACTUAL CONTRACTOR OF THE PARTY
ouration: 201	158 / Start 08	/10/2020 08:	55 / End 0	8/10/2020 09:15 / H	Hrs .33 / Gals	5.5	
_							
Potential Dang	gers to Hum	an Health a	nd Safety o	or the Environmen	t: No Signific	cant Dangers	
Actions Taker							
Monitoring Da	ita: Data sho	uld be attac	hed or sub	mitted to TCEQ w	hen availab	le.	
	ye	s	no	Field Measurer	ments		
	ye	s	<u> </u>	Laboratory Sar	nples		
	ye	s	no	Fish Kill, If yes,	, estimated nur	mber killed	
ctions Taker	to Mitigate	Adverse Eff	ects: Area	Cleaned and Disi	nfected		
ctions Taker	to Correct t	he Problem	and Preve	ent Recurrence: 8	Inch Sewer	Main, Unstopp	ed Main
erification In	tormation						
nformation Re	eported By _	F	Richard Sa (Name)	ntos		LC/TV OPERA	FOR III
				108	MX	2.14	8/11/22
ate Reported		/10/2020	s	ignature:	6461	741	(005 5200
CEQ 0501 (Nov	ember 5, 2002)	If the noncon	npliance is an	unauthorized discharge	ge from a wast	ewater collection s	system, use

TCEQ Region 13 Phone: 490-3096

TCEQ Region 13 Fax: 545-4329