

November 24, 2020

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (R6-ECDWA) Water Enforcement Branch U.S. EPA Region 6 1201 Elm Street, Suite 500 Dallas, TX 75270-2102 Via U.S. Certified Mail RRR# 7017 0530 0001 0086 6914

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on November 24, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely,

Jeffrey J. Haby, P.E.

Vice President

Production & Treatment

Enc. as stated



November 24, 2020

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611 Washington, D.C. 20044-7611

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 6907

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on November 24, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Vice President

Production & Treatment

Enc. as stated

Water Quality Noncompliance Notification

X Unauthorized Discharge of Wastewater	Reportable Effluent Violation Othr
General Information	
Entity Name: San Antonio Water System	Telephone: 210-233-3274
X Permitte	Subscriber
TCEQ Region: 13 County: Bexar	Permit Number 10137-008-Salado Creek
Noncompliance Summary	
Description of Noncompliance (include location, discharge): The address of the spill was at 270 Ant Salado Creek Ferg: 192D7	scharge route, and estimated volume if an unauthorized trim Dr, Approximately 255 Gallons Spilled Into Storm Drain
Case #: 5380 / SR#: 3502479 / INSP#: 659196 / W	/O#: 1895520 / SRC: Sewer Main 990831 990873
Cause of Noncompliance: Contractor	
Duration: Sewer Manhole 990831 / Start 11/19/2	2020 17:39 / End 11/19/2020 18:30 / Hrs .85 / Gals 255
Potential Dangers to Human Health and Safety	y or the Environment: No Significant Dangers
Actions Taken	
Monitoring Data: Data should be attached or si	ubmitted to TCEQ when available
A Company of the Comp	Field Measurements
	o Laboratory Samples
	o Fish Kill, If yes, estimated number killed
	Il Contained, Flushed Area with H2O, Clean Up Is Ongoing
Actions Taken to Mitigate Adverse Effects. Spi	il Contained, Flushed Alea With H2O, Clean Op is Ongoing
	vent Recurrence: 10 Inch Sewer Main, Unstopped Main,
Work Order Created To Repair Main	
Verification Information	
	in and the second secon
Information Reported By Robert Rodr (Name)	riguez Jr / LC/TV OPERATOR II (Title)
Date Reported11/19/2020	Signature: Muth Snn 11/24/20
TCEQ 0501 (November 5, 2002) If the noncompliance is	ANNETTE POURON - DE ONS SUSPINI an unauthorized discharge from a wastewater collection system, usel puril the treatment plant to which the collection system is tied.
TCEQ Region 13 Phone: 490-3096	TCEQ Region 13 Fax: 545-4329

Water Quality Noncompliance Notification

X Unauthorized Discharge of Wastewate	r Reportable Effluent Violation Othr	
General Information		
Entity Name: San Antonio Water System	Telephone: 210-233-3274	
X Permitte	Subscriber	
TCEQ Region: 13 County: Bexar	Permit Number 10137-033-Steven M. Clouse	
Noncompliance Summary		
Description of Noncompliance (include location, didischarge): The address of the spill was at 1167 A Street Ferg: 212A5	ischarge route, and estimated volume if an unauthorized at And T Center Pkwy, Approximately 57 Gallons Spilled Into	
Case #: 5400 / SR#: 3503152 / SRC: Sewer Main 31421 46196		
Cause of Noncompliance: Grease		
Duration: Sewer Manhole 31421 / Start 11/20/2	020 10:53 / End 11/20/2020 11:50 / Hrs .95 / Gals 57	
Potential Dangers to Human Health and Safe	ty or the Environment: No Significant Dangers	
	, and a second s	
Actions Taken		
Monitoring Data: Data should be attached or s		
	no Field Measurements	
	no Laboratory Samples no Fish Kill, If yes, estimated number killed	
Actions Taken to Mitigate Adverse Effects: Ar	ea Cleaned and Disinfected	
Actions Taken to Correct the Problem and Pre	event Recurrence: 8 Inch Sewer Main, Unstopped Main	
Verification Information		
Information Reported By Guadalupe		
(Name	(Title)	
Date Reported11/20/2020	Signature: 11/23/20 ANNETTE DURAN 215, 005 \$100 004	
TCEQ 0501 (November 5, 2002) If the noncompliance is the permit number of the	ANNETTE DURAN, FU, ONS SUPP END S an unauthorized discharge from a wastewater collection system, use the treatment plant to which the collection system is tied.	
TCEQ Region 13 Phone: 490-3096	TCEQ Region 13 Fax: 545-4329	