

#### November 27, 2020

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (R6-ECDWA) Water Enforcement Branch U.S. EPA Region 6 1201 Elm Street, Suite 500 Dallas, TX 75270-2102

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 6921

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

#### Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on November 27, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Jeffrey J. Haby, P.E.

Vice President

Production & Treatment

Enc. as stated



### November 27, 2020

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611 Washington, D.C. 20044-7611

Via U.S. Certified Mail RRR# 7017 0530 0001 0086 6938

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San

Antonio Division

#### Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on November 27, 2020 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Jeffrey J. Haby, P.E.

Vice President

Production & Treatment

Enc. as stated

## Water Quality Noncompliance Notification

X Unauthorized Discharge	OI Wastewater	Reportable Effluent	Violation Othr
General Information			
Entity Name. San Antonio Wa	ater System	Telephone	210-233-3274
X Permitte	simulation.	Subscriber	
TCEQ Region: 13 Cou	inty: Bexar Pe	rmit Number 10	137-003-Leon Creek
Noncompliance Summary			
Description of Noncompliance (inc discharge). The address of the spil Channel Ferg 227D2	lude location, discharge I was at 2303 Observat	route, and estimated volu ion Dr. Approximately 895	me if an unauthorized Gallons Spilled Into Drainage
Case #: 5440 / SR#: 3507444 / INS	3P#: 6599017 SRC: Se	wer Main 71176 70948	
Cause of Noncompliance: Great	35 <b>e</b>		
Duration: Sewer Manhole 41314	0 / Start 11/24/2020 23	01 / End 11/25/2020 02	00 / Hrs 2.98 / Gals 895
(man/cm/manasasasasasasasasasasasasasasasasasasa			
***************************************	***************************************	***************************************	
Paragraphic Company of the Company o		*** * * * * * * * * * * * * * * * * *	
Potential Dangers to Human He	alth and Safety or the	Environment: <u>No Signi</u>	icant Dangers
	Marine		
Actions Taken			
Monitoring Data: Data should be	e attached or submitte	ed to TCEQ when availa	ble
Xyes	no no	Field Measurements	
yes	<u>X</u> no	Laboratory Samples	
yes yes	X no	Fish Kill, If yes, estimated n	imber killed
Actions Taken to Mitigate Adve	rse Effects: <u>Area Clea</u>	ned and Disinfected, Fl	ushed Area with H2O
*******			
	***************************************		
Actions Taken to Correct the Pr	oblem and Prevent R	ecurrence: <u>10 Inch Sev</u>	er Main, Unstopped Main
	***************************************		
Verification Information			
Information Reported By	Eric M Viera		LC/TV OPERATOR III
	(Name)	/	Tale)
Oste Reported 11/24/2	020 Signa	rure <u>1000</u>	<u> Wu 11/25,</u>
TCEQ 0501 (November 5, 2002) If the	noncompiance is an unau	HVVE 77 / thonzed discharge from a Wa	Sewater collection system use
	amit number of the treatm	ent plant to which the collecti	xn system is fied
TCEQ Region 13 Phone: 490-30	<b>J96</b>	ie en la valor <b>to</b> l	EQ Region 13 Fax: 545-43

# Water Quality Noncompliance Notification

""X Unauthorized Discharge	of Wastewater	Reportable E	ffluent Violation	Othr
General Information				
Entity Name: San Antonio W	/aler System	Telephone	× 210-233-32	274
X Permitte		Subscriber	siyan jarahan arahan jarahan jarah	inanainininanainin
TCEQ Region: 13 Co	unty: Bexar p	ermit Number	10137-033-Steven M. (	Clouse
Noncompliance Summary				
Description of Noncompliance (in discharge): The address of the sp Ferg: 190C3	clude location, discharg ill was at 5 Flintstone C	e route, and estimate t, Approximately 94	id volume if an unauthoriz Gallons Spilled Into Storm	ed Drain
Case #: 5460 / SR#: 3507883 / IN	ISP#: 659930 / WO#: 1	270371 / SRC: Sewe	r Main 564536 375669	
Cause of Noncompliance: Str				
Duration Sewer Manhole 5645	31 / Start 11/25/2020 1	1:31 / End 11/25/20	20 13:05 / Hrs 1.57 / Gal	ls 94
	• • • • • • • • • • • • • • • • • • •			
-				
Potential Dangers to Human H	ealth and Safety or th	ie Environment: <u>No</u>	Significant Dangers	
Actions Taken				
Monitoring Data: Data should t	e attached or submit	ted to TCEQ when	available.	
X yes	no	Field Measurements		•
yes	X no	Laboratory Samples		
yes	Х по	Fish Kill, If yes, estin	nated number killed	· ·
Actions Taken to Mitigate Adve	erse Effects: <u>Soill Cor</u>	itained, Flushed Ar	ea with H2O, Cleanup C	)ngoing
Actions Taken to Correct the F Main, Unstopped Main	roblem and Prevent i	Recurrence: 8 Inch	Sewer Main, Repairing	<u>//Repaired</u>
Verification Information				
Information Reported By	Eduardo Martine	<b>?Z</b>	LC/TV OPERATO	OR III
Date Reported 11/25/	(Name)	ature: AU		1/27/22
TCEO 0501 (November 5, 2002) If the		かからて outhorized discharge fro	m a wastewater collection sy	1252/12012 Clem, 18872012
TCEQ Region 13 Phone: 490-3		ison betien in minimi ing	TCEQ Region 13 Fax	x 545-4329