

March 9, 2021

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611 Washington, D.C. 20044-7611

Via U.S. Certified Mail RRR# 7006 2150 0005 7541 4494

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on March 9, 2021 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely,

Vice President

Production & Treatment

Enc. as stated



March 9, 2021

Via U.S. Certified Mail

RRR# 7006 2150 0005 7541 4487

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (R6-ECDWA) Water Enforcement Branch

U.S. EPA Region 6 1201 Elm Street, Suite 500

Dallas, TX 75270-2102

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on March 9, 2021 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely

Vice President

Production & Treatment

Enc. as stated

Water Quality Noncompliance Notification

| X Una | authorized Disc | harge of Wa | astewater | Reportable E | ffluent Violation | Othr |
|--------------|-------------------------|----------------------|-----------------------|--|----------------------------|------------------|
| eneral Ir | nformation | | | | | <u> </u> |
| Entity Nan | ne: San Anto | onio Water S | ystem | Telephon | e: 210-23 | 3-3274 |
| X Perr | nitte | | | Subscriber | | |
| TCEQ Re | gion: 13 | County: | Bexar | Permit Number | 10137-040-Med | o Creek |
| Voncomp | liance Summar | у | | | | |
| | The address of | | | arge route, and estimat Valley Dr. Approximat | | |
| Case #: 71 | 60 / SR#: 36142 | | 72761 / WO# | #: 1930019 / SRC: Sewe | er Main 71603 71483 | |
| Cause of I | Noncompliance | : Structural | | | | |
| | | | | | | |
| Duration: | Sewer Service | Line 383317 | / Start 03/04/ | /2021 09:00 / End 03/0 | 04/2021 09:15 / Hrs .: | 25 / Gals 300 |
| | | 183-30 -0 11- | | 3 | | |
| | | | - Neditalii | | | |
| Potential I | ————— Dangers to Hur | ———— nan Health ຄ | and Safety o | or the Environment: N | o Significant Dange | rs |
| | | | | | | |
| | | | | | | |
| Actions T | | | | | | . <u>.</u> |
| Monitoring | ر Data: Data sh | iould be atta | | mitted to TCEQ wher | | |
| | | | X no | Field Measurement Laboratory Sample | | |
| | | yes yes | X no | | s imated number killed | |
| Actions T | | | | | _ | L Eluphod Area |
| with H2O | aken to willigati | a Adverse Ei | nects: <u>Spill (</u> | Contained, Area Clea | ned and Distillected | i, Flustied Alea |
| - | | | | | | |
| Actions T | aken to Correc | t the Probler | n and Preve | ent Recurrence: 8 Inc | <u>ch Sewer Main, Uns</u> | topped Main |
| | | | | , | | |
| Verification | on Information | | | | | |
| Informatio | on Reported By | , R | Ricardo J Sa | nchez / | LC/TV OP | ERATOR II |
| | | ¥ | (Name) | 111.111 | 1 BUEF | MAHM |
| Date Rep | orted | 3/4/2021 | S | Signature: | Y VICE P | RESIDEM |
| | | 02) If the nonco | ompliance is ar | unauthorized discharge | rom a wastewater collect | tion system, use |
| | 3 10 | the permit r | number of the t | treatment plant to which the | e collection system is tie | d. |

TCEQ Region 13 Phone: 490-3096 TCEQ Region 13 Fax: 545-4329

Water Quality Noncompliance Notification

| X Unauthorized D | ischarge of Wastewater | Reportable Effl | uent Violation (| Othr |
|---------------------------------|---|---|--|----------|
| Seneral Information | | | | |
| Entity Name: San Ar | ntonio Water System | Telephone: | 210-233-3274 | |
| X Permitte | Ngophonon | Subscriber | | |
| TCEQ Region: 13 | County: Bexar | Permit Number 1 | 0137-033-Steven M. Clous | se |
| Noncompliance Summ | nary | | | |
| discharge): The address | iance (include location, disch of the spill was at 6411 Vanc ns Spilled Into Street Ferg: | e Jackson , Over The Edv | l volume if an unauthorized wards Aquifer Transition Zone | <u> </u> |
| Case #: 7161 / SR#: 361 | 4516 / INSP#: 672774 / WO# | : 1930047 / SRC: Sewer | Main 6555 6474 | |
| Cause of Noncompliar | nce: Structural | | | |
| | | | | |
| Duration: Sewer Manh | ole 6555 / Start 03/04/2021 (| 9:16 / End 03/04/2021 | 10:45 / Hrs 1.48 / Gals 178 | |
| 3 | | | | 100 |
| | | - Charles | | |
| Detectiel Decrees to I | | . H Fardinana at No. | 0::5 | |
| Potential Dangers to F | luman Health and Safety o | r the Environment: No. | Significant Dangers | |
| | | | | |
| Actions Taken | | | | |
| Monitoring Data: Data | should be attached or sub | mitted to TCEQ when a | available. | |
| | yes X no | Field Measurements | | |
| | yes X no | Laboratory Samples | | |
| | yes X no | Fish Kill, If yes, estima | ated number killed | |
| Actions Taken to Mitig with H2O | ate Adverse Effects: <u>Spill (</u> | Contained, Area Cleane | ed and Disinfected, Flushed | d Area |
| Actions Taken to Corr | ect the Problem and Preve | nt Recurrence: 8 Inch | Sewer Main, Unstopped M | ain |
| | | | | |
| Verification Informatio | n | | | |
| Information Reported | | yar Ir | LC/TV OPERATOR III | - 2 |
| simulati i topoitod | (Name) | 11.11 | 11 IDEE MA | 184 |
| Date Reported | 3/4/2021 S | ignature: | My VICE PREDICT | gy 1H |
| TCEQ 0501 (November 5, | 2002) If the noncompliance is an the permit number of the t | unauthorized discovarge from reatment plant to which the d | a wastewater collection system collection system is tied. | , use |
| TCEQ Region 13 Pho | | · | TCEQ Region 13 Fax: 54 | 15-4329 |