

May 7, 2021

U.S. Department of Justice Environmental Enforcement Section Environment and Natural Resources Division P.O. Box 7611 Washington, D.C. 20044-7611

Via U.S. Certified Mail RRR# 7006 2150 0005 7541 2520

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San

Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on May 7, 2021 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Jeffrey J**V**Haby, P.B Vice President

Production & Treatment

Enc. as stated



May 7, 2021

U.S. Environmental Protection Agency, Region VI Attn: Ms. Judy Edelbrock (R6-ECDWA) Water Enforcement Branch U.S. EPA Region 6 1201 Elm Street, Suite 500 Dallas, TX 75270-2102 Via U.S. Certified Mail RRR# 7006 2150 0005 7541 2537

Re: DOJ Case No. [90-5-1-1-09215]

Consent Decree

Date of Entry: October 15, 2013

CA No. 5:13-cv-00666-DAE, United States of America and State of Texas v. San Antonio Water System, in the United States District Court for the Western District of Texas, San Antonio Division

Dear Sir/Madam:

Section 12 b. of the above-referenced Consent Decree requires that within 90 days after Lodging the San Antonio Water System shall provide a copy of any five-day report submitted under its TPDES permits to the United States Environmental Protection Agency at the same time the report is submitted to the Texas Commission on Environmental Quality. Copies of five-day reports submitted to TCEQ on May 7, 2021 are attached and are provided in compliance with Consent Decree requirements.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering such information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Sincerely.

Jeffrey J. Haby, P.E.

Production & Treatment

Enc. as stated

Water Quality Noncompliance Notification

X Un	authorized Discharge of Wastewater	Reportable Effluent Violation	Othr
General I	nformation		
Entity Nan	ne: San Antonio Water System	Telephone: 210-233-	3274
X Pen	mitte	Subscriber	
TCEQ Re	gion: 13 County: Bexar	Permit Number 10137-033-Steven M	. Clouse
Noncomp	liance Summary		
discharge):		arge route, and estimated volume if an unauthonena St, Approximately 320 Gallons Spilled Into	
Case #: 78	20 / SR#: 3686668 / INSP#: 681209 / SRC	: Sewer Main 480897 480896	
Cause of	Noncompliance: Grease		
Duration:	Sewer Manhole 32460 / Start 05/04/2021	07:26 / End 05/04/2021 08:30 / Hrs 1.07 / G	als 320
Potential [Dangers to Human Health and Safety o	r the Environment: No Significant Dangers	
Actions Ta	aken		
		mitted to TCEO when available	
MONITORING	Data: Data should be attached or sub	Field Measurements	
	yes X no	Laboratory Samples	
8	yes X no	Fish Kill, If yes, estimated number killed	
Actions 1 a	aken to Mitigate Adverse Effects: <u>Area</u>	Cleaned and Disinfected, Flushed Area wit	n H2O
Actions Ta	aken to Correct the Problem and Preve	nt Recurrence: 8 Inch Sewer Main, Unstor	ped Main
			-
Verificatio	n Information		
		LC/TV/ODED	ATOR III
mormado	n Reported By Felipe Saldiv (Name)	var Jr / LC/TV OPER	4/10/
Data Da	5/A/2024 S	ignature: WINTER VICE PA	EDIOFAL AL
9.53	7007070	(7/1/19)	
FCEQ 0501		unauthorized discharge from a wastewater collection	system, use

TCEQ Region 13 Fax: 545-4329

TCEQ Region 13 Phone: 490-3096

Water Quality Noncompliance Notification

X Unauthorized Discharge of Was	tewater Reportable E	Effluent Violation Othr	
General Information			
Entity Name: San Antonio Water Sys	stem Telephon	ne: 210-233-3274	
X Permitte	Subscriber		
TCEQ Region: 13 County:	Bexar Permit Number	10137-033-Steven M. Clouse	
Noncompliance Summary			
Description of Noncompliance (include local discharge): <u>The address of the spill was at</u> 191A5			
Case #: 7860 / SR#: 3689986 / SRC: Sewe	er Main 24083 24084		
Cause of Noncompliance: Rain Event			
Duration: Sewer Manhole 24083 / Start	05/03/2021 09:52 / End 05/03/20	21 09:52 / Hrs 0 / Gals 1121	
Potential Dangers to Human Health an	d Safety or the Environment: N	o Significant Dangers	
Actions Taken			
Monitoring Data: Data should be attach	ned or submitted to TCEQ wher	n available.	
yes X	Field Magazirament		
yes X	no Laboratory Samples	S	
yesX	no Fish Kill, If yes, esti	imated number killed	
Actions Taken to Mitigate Adverse Effe	ects: Area Cleaned and Disinfec	cted. Diluted By Heavy Rain Water	
Actions Taken to Correct the Problem	and Prevent Recurrence: 10 In	ch Sewer Main, Monitored Area	
Verification Information			
Information Reported By	Eloy Saldivar	WASTEWATER TECHNICIAN IJI	
	(Name)	1) / JEPAME) HAID!	
Date Reported5/3/2021	Signature:	19/ VILE PRES PROM	0
TCEQ 0501 (November 5, 2002) If the noncom	pliance is an unauthorized discharge fr	om a wastewater collection system, use	K
the permit nur	mber of the treatment plant to which the	e collection system is tied.	

TCEQ Region 13 Fax: 545-4329

TCEQ Region 13 Phone: 490-3096